DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 59 2022 Reas	on for Maintenance:	98531970	5	
Property Address: 23780 Flag T	Av.N. Pro	perty Owner's Name:	UB Brown	
Municipality: Forest Lake	State Zip Co	de GEO	Code/Property I.D. #:	
What was done to the system (A PERMIT	easurem e nts (musube a	ompleted if tanks NOT pumped).	
Tank(s) Pumped	Liquid Level of Ta	At in clus	in C	KARLEST
Sludge and scum measured.	Elquid Level of 1	erfik in. Sludge	Level in. Scum Level	in. —
Do tanks need to be pumped? Yes No (If no provide measurem	Total (Sludge + S	cum) / Liquid L	evel = % Sludge & Scum	
The provide measurement			* Tank must be assessed that	
1. Access used to remove septage: Main			 Tank must be pumped if this is greater than 25%. 	value
2. If maintenance hole was used, were all cov	ers securely replaced? –	Yes No please ex	plain	
Explanation:				
3. If owner refuses to allow a Subsurface So them complete and sign the following st	ewage Treatment Syste atement:	m (SSTS) to be pumped	through the maintenance hole, h	ave
l,	(owner's name) refuse to	allow the removal of col	ids and liquids through the mainten	
hole. I understand that removal of solids as	nd liquids through other	access points is not consi	dered maintenance	ance
4. Is the tank designed as a leaky tank? examp			acted maintenance.	
Tank#1 Yes No Verificatio Metho				
Tank#2 Yes No Verificatio Metho	od Used:			-
5. Is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretrea	tment or pump tank be	low the operating depth or evider	nce of
Tank	Leaking Out	Leaking In	Cover Down	
Septic/Holding Tank #1	Yes No		Cover Damage	
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	Yes No	Yes No	Yes No	
6. How many gallons of septage were remo				
Tank #1 <u>1500</u> Tank #2	Pretreatment Ta		ımp Tank	
7. Other information: List any troubleshooti	ng, minor repairs cond	ucted, tank safety conce	erns, or other concerns.	
B. Certification: I hereby certify as a State of Mande the observations, of	Ainnesota certified SSTS or directly supervised other	Maintainer that I persona	lly conducted the work	
Maintainer's Name: Olson's Sewer Service, I			Street NE, Forest Lake, MN	
Maintainer's License #: 216 Mainta	iner's Phone #: 651-464	I-2082	0	
Maintainer's Signature	60	Date: 5/	9/22	
7		/		