ess Name: SS Septic Solutions, LLC.		Date:	6/28/2022
npact on public health – Co	ompliance com	ponent #1 of 5	
Compliance criteria:		Attached supporting documentation:	
System discharges sewage to the ground surface	☐ Yes ☑ No	☐ Other: ☐ Not applicable	
System discharges sewage to drain tile or surface waters.	☐ Yes ⊠ No		
System causes sewage backup into dwelling or establishment.	☐ Yes ⊠ No		
escribe verification methods and	results:		
nk integrity — Compliance	component #2	of 5	
nk integrity — Compliance Compliance criteria:	component #2		n:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit,	component #2	of 5 Attached supporting documentation ⊠ Empty tank(s) viewed by inspector	n:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?		Attached supporting documentation	n: Meyers
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their		Attached supporting documentation Empty tank(s) viewed by inspector	Meyers
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes ⊠ No	Attached supporting documentation Empty tank(s) viewed by inspector Name of maintenance business:	Meyers
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes ⊠ No	Attached supporting documentation Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance busines	Meyers ess: 06/28/2022
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth?	☐ Yes ⊠ No	Attached supporting documentation Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance busines Date of maintenance: Existing tank integrity assessment (Attached)	Meyers ess: 06/28/2022
	☐ Yes ⊠ No	Attached supporting documentation Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance busines Date of maintenance: Existing tank integrity assessment (Attached)	Meyers ess: 06/28/2022 ech) in three years)
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth?	☐ Yes ⊠ No	Attached supporting documentation Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance busines Date of maintenance: Existing tank integrity assessment (Attached Date of maintenance (mm/dd/yyyy): (must be with (See form instructions to ensure assess Minn. R. 7082.0700 subp. 4 B (1))	Meyers ess:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth?	☐ Yes ⊠ No	Attached supporting documentation Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance busines Date of maintenance: Existing tank integrity assessment (Attached Date of maintenance (mm/dd/yyyy): (must be with (See form instructions to ensure assess Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not nece	Meyers ess: 06/28/2022 ech) in three years) sment complies w ssary – explain belo
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth?	☐ Yes ⊠ No	Attached supporting documentation Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance busines Date of maintenance: Existing tank integrity assessment (Attached) Date of maintenance (mm/dd/yyyy): (See form instructions to ensure assess Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not nece	Meyers ess: 06/28/2022 ech) in three years) sment complies wassary – explain belo
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks:	☐ Yes ⊠ No	Attached supporting documentation Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance busines Date of maintenance: Existing tank integrity assessment (Attached Date of maintenance (mm/dd/yyyy): (must be with (See form instructions to ensure assess Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not nece	Meyers ess: 06/28/2022 ech) in three years) sment complies wassary – explain belo
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks:	☐ Yes ⊠ No	Attached supporting documentation Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance busines Date of maintenance: Existing tank integrity assessment (Attached Date of maintenance (mm/dd/yyyy): (must be with (See form instructions to ensure assess Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not nece	Meyers ess: 06/28/2022 ech) in three years) sment complies wassary – explain belo
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks:	☐ Yes ⊠ No	Attached supporting documentation Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance busines Date of maintenance: Existing tank integrity assessment (Attached Date of maintenance (mm/dd/yyyy): (must be with (See form instructions to ensure assess Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not nece	Meyers ess: 06/28/2022 ech) in three years) sment complies wassary – explain belo
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks:	☐ Yes ⊠ No	Attached supporting documentation Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance busines Date of maintenance: Existing tank integrity assessment (Attached Date of maintenance (mm/dd/yyyy): (must be with (See form instructions to ensure assess Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not nece	Meyers ess: 06/28/2022 ech) in three years) sment complies wassary – explain belo