npact on public health — C Compliance criteria:	Ompile	ince com		
System discharges sewage to the ground surface	☐ Yes	⊠ No	Attached supporting documentation:	
System discharges sewage to drain tile or surface waters.	☐ Yes	⊠ No	☐ Not applicable	
System causes sewage backup into dwelling or establishment.	☐ Yes	⊠ No		
Describe verification methods and	l results:			
nk integrity – Compliance	comp	onent #2	of 5	
nk integrity – Compliance Compliance criteria:	comp	onent #2		
Compliance criteria: System consists of a seepage pit,	comp	onent #2 ⊠ No	of 5 Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector	
Compliance criteria:	T		Attached supporting documentation:	Meyers
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes		Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector	-
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes	⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business:	
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes	⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business	6/28/2022
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes	⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance: Existing tank integrity assessment (Attach Date of maintenance	6/28/2022
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes	⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance: Existing tank integrity assessment (Attach	:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth?	☐ Yes	⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance: Existing tank integrity assessment (Attach Date of maintenance	:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth?	☐ Yes	⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance: Existing tank integrity assessment (Attach Date of maintenance (mm/dd/yyyy): (See form instructions to ensure assessment) Minn. R. 7082.0700 subp. 4 B (1))	: 6/28/2022) three years) ent complies w
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth?	☐ Yes	⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance: Existing tank integrity assessment (Attach Date of maintenance (mm/dd/yyyy): (See form instructions to ensure assessment)	: 6/28/2022) three years) ent complies wi
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth?	☐ Yes	⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance: Existing tank integrity assessment (Attach Date of maintenance (mm/dd/yyyy): (must be within to (See form instructions to ensure assessment Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necessal	: 6/28/2022) three years) ent complies w
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks:	☐ Yes	⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance: Existing tank integrity assessment (Attach Date of maintenance (mm/dd/yyyy): (must be within to (See form instructions to ensure assessment Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necessal	: 6/28/2022) three years) ent complies w