Property Ad	dress: 16845 20TH ST S, CITY OF LAKE ST CROIX BEACH		
Business Na	ame: SS Septic Solutions, LLC.	Date:	7/6/2022
3. Other	compliance conditions – Compliance component #3 of 5		
3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unsecured? ☐ Yes ☐ Unknown			
3b. Oth	er issues (electrical hazards, etc.) to immediately and adversely impact public health or safety	? 🗌 Yes	⊠ No □ Unknown
3c. Sys	tem is non-protective of ground water for other conditions as determined by inspector?	☐ Yes	⊠ No
3d. Sys	em not abandoned in accordance with Minn. R. 7080.2500?	☐ Yes	⊠ No
Des	cribe verification methods and results:		
Atta	ched supporting documentation: Not applicable		
4. Opera	ting permit and nitrogen BMP* – Compliance component #4 of	5 × N	lot applicable
		(A)	below is required
	tem required to employ a Nitrogen BMP specified in the system design? \square Yes \square No If \square = Best Management Practice(s) specified in the system design	"yes", B	below is required
	swer to both questions is "no", this section does not need to be completed.		
	nce criteria:		
	ve the operating permit requirements been met?		
D. IS U	ne required nitrogen BMP in place and properly functioning? Yes No		
Des	scribe verification methods and results:		
Att	ached supporting documentation: Operating permit (Attach)		
9 133			