## Washington County

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

| This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed |   |  |             |                             |                  |
|--|---|--|-------------|-----------------------------|------------------|
| prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.            |   |  |             |                             |                  |
| Date of Maintenance: 14 July 22 Reason for Maintenance: Reg Maint  |   |  |             |                             |                  |
| Property Address: 17525 Key Stone Ave N Property Owner's Name: Crain That he rt  |   |  |             |                             |                  |
| Municipality: Hugo ZIP: 55038 Property Identification Number:  |   |  |             |                             |                  |
| Maintenance Permit No: <u>4171: 27545</u> Maintainer Name and License No. <u>Smilie's Sewer Service / L 2428</u>       |   |  |             |                             |                  |
|  |   |  |             |                             |                  |
| Maintenance Performed  |   | Tank Measurement (must be completed if tanks NOT pumped) |             |                             |                  |
| X Tank(s) Pumped   |   | Liquid Level of Tank in                                  |             |                             |                  |
| Sludge and scum measured   |   | Sludge Level in Tank in Scum Level in Tank in            |             |                             |                  |
| Do tanks need to be pumped?  |   | Sludge + Scum / Liquid Level X 100                       |             |                             |                  |
| Yes No (if no pro  | vide measurements)  | = % Sludge & Scum  | Ta          | n <u>ks must be pumpedi</u> | f 25% or greater |
| 1. Access used to remove septage: Maintenance Hole $\underline{m{\chi}}$ Other (enter authorization code)              |   |  |             |                             |                  |
| 2. Were all covers securely replaced? X Yes No   |   |  |             |                             |                  |
| 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or    |   |  |             |                             |                  |
| evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes _YNo                                |   |  |             |                             |                  |
|  | Tank  | Leaking Out  | Leaking In  | Cover Damage                |                  |
| Sentic   | CONTRACTOR |  |             |                             |                  |
| Зерис/   | - Tiolding Falls #1   | Yes <u> </u>   | Yes _ No    | Yes _\_No                   |                  |
| Septic/  | Holding Tank #2   | Yes No   | Yes No      | Yes No                      |                  |
| Pretrea  | atment Tank   | Yes No   | Yes No      | Yes No                      |                  |
| Pump 7   | Гank<br>-   | Yes No   | Yes No      | Yes No                      |                  |
| 4. How many gallons of septage were removed?   |   |  |             |                             |                  |
| Tank #1 <u>/000</u> gal  | gal Pretreatment tar  | nkgal  | . Pump Tank | gal                         |                  |
| 5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.      |   |  |             |                             |                  |
|  |   |  |             |                             |                  |
|  | . //  | 10015  |             |                             |                  |
| 6. Location of septage disposa   | al: <u>1910</u>   | Appled   |             |                             |                  |
|  |   | Smilie's Sewer Serv                                      | vice .      |                             |                  |
| P.O. Box 100<br>Scandia, MN 55073  |   |  |             |                             |                  |
|  | P: 651-4  | 33-3934 License N  |             |                             |                  |
| Maintenance activities must be reported to the Department within 90 days.  |   |  |             |                             |                  |
| White Copy-Maintainer submits to Washington County / Pink Copy-Property Owner Record                                   |   |  |             |                             |                  |
|  |   |  |             | 15                          |                  |