## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT

Date of Maintenance 7 Reas	on for Maintenance: 🔾	9897 62816	5	
Property Address: 9869 Hadden	Glade Ave Pro	pperty Owner's Name:	John Blanchord	
Municipality: Grant	State MN Zip Co	ode 55110 GEO	Code/Property I.D. #:	
	st et fact einkeld	easurements (must be c	ompleted (Ktanks NO upump	ed) save
tank(s) Pumped	Liquid Level of T	arlik in. Sludge	Level in. Scum Level	
Sludge and scum measured.  Do tanks need to be pumped?		Jidage	Level in. Scum Level	in.
Yes No (If no provide measurem	ents) Total (Sludge + S	Scum) / Liquid Le	evel = % Sludge & Sc	um
1. Access used to remove septage: Main	tenance Hole Othe	r (Go to #3 below)	* Tank must be pumped in	this value
2. If maintenance hole was used, were all cov	ers securely replaced?	Yes No please exp	is greater than 25%. Plain	
Explanation:	•	<b>,</b> •		
3. If owner refuses to allow a Subsurface Se them complete and sign the following st	ewage Treatment Systematement:	em (SSTS) to be pumped	through the maintenance ho	le, have
		o allow the removal of set	ور و در در در المساولة	
hole. I understand that removal of solids ar	ed liquids through other	access points is not consi	ds and liquids through the mai	ntenance
4. Is the tank designed as a leaky tank? examp	le: seepage pit, cesspool,	drywell, leaching pit	acted maintenance.	
Tank#1 Yes No Verificatio Metho				
Tank#2 Yes No Verificatio Metho	od Used:			2
5. Is there evidence of tank leakage from a s		etment or numn tank he	out the energting denth or a	
damaged, cracked, or structurally unsour	id maintenance hole co	overs?	on the operating depth of el	ridence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	Yes No	☐ Yes ☐ No	
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	Yes No	Yes No	Yes No	
5. How many gallons of septage were remov	red?		2 %	
Tank #1 1500 Tank #2 1000	Pretreatment Ta	nnk Pu	mp Tank 206	
7. Other information: List any troubleshooti	ng, minor repairs cond	ucted, tank safety conce	rns, or other concerns.	
<ul> <li>Certification: I hereby certify as a State of N and made the observations, c</li> </ul>	linnesota certified SSTS or directly supervised otl	Maintainer that I personal ners in the performance of	ly conducted the work this job.	
Maintainer's Name: Olson's Sewer Service, I	nc. Maintaine	er's Address: 17638 Lyons	Street NE, Forest Lake, MN	
Maintainer's License #: 216 Mainta	iner's Phone #: 651-46	4-2082	×	
Maintainer's Signature	7	Date: 7	-12.22	