DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT, 2502028183

Date of Maintenance 7/20/22 Re	ason for Maintenance:			
Property Address: 23840 St.Cr	mote N PI	operty Owner's Name:	Kathleen Muler	
Municipality: Scandia	State Zip C	ode <u>95073</u> GEO	Code/Property I.D. #:	
Les Whatewas done to the system of	i janki	lee su rements(mittele	တက်ပြင်ပါနေကိုလုပ်တွေက	
Tank(s) Pumped		- A.		as Caster
Sludge and scum measured. Do tanks need to be pumped? Yes No (If no provide measure	Liquid Level of			-
1. Access used to remove septage:		er (Go to #3 below)	* Tank must be pumped	
2. If maintenance hole was used, were all co			is greater than 25%.	
Explanation:	, 15,115500	ino pieuse es	spiain	
3. If owner refuses to allow a Subsurface sthem complete and sign the following states.	Sewage Treatment Systematics S	em (SSTS) to be pumper	i through the maintenance h	ole, have
l, ·		e allamah a samu di d		
hole. I understand that removal of solids a	owner's manney, refuse t	o allow the removal of so	lids and liquids through the m	aintenance
4. Is the tank designed as a leaky tank? exam	ple: seepage nit cessool	dravell leaching pit	idered maintenance.	
Tank#1 Yes No Verificatio Meth		arywen, reaching pit		
Tank#2 Yes No Verificatio Meth	od Used:			
5. Is there evidence of tank leakage from a damaged, cracked, or structurally unson	septic, holding, pretre	atment or pump tank be	low the energting densh or	
and a second and a second and a second	nd maintenance hole co	overs?	are operating depth of e	ividence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	☐ Yes ☐ No	Yes No	
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	Yes No	Yes No	Yes No	
. How many gallons of septage were remo	ved?			
Tank#1 /2007) Tank#2	Pretreatment Ta	nk Pl	ımp Tank	
Other information: List any troubleshoot	ing, minor repairs cond	ucted, tank safety conce	erns, or other concerns.	
Certification: I hereby certify as a State of I and made the observations,	Minnesota certified SSTS or directly supervised other	Maintainer that I personal	ly conducted the work	
Maintainer's Name: Olson's Sewer Service,			Street NE, Forest Lake, MN	
Maintainer's License #: 216 Maintainer	niner's Phone #: 651-464		Y	
Maintainer's Signature	Min	Date:	20-22	
d	1 8			