	Property Address: 6751 Geneva Ave. S. Cottage Grove	
Е	Business Name: SS SepticSolutions, LLC.	Date: 7/22/2022
3.	 Other compliance conditions – Compliance component #3 of 5 	
3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unsecured?		ecured?
	☐ Yes ☐ No ☐ Unknown	
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safet	y? ☐ Yes ☑ No ☐ Unknown
	3c. System is non-protective of ground water for other conditions as determined by inspector?	☐ Yes ☑ No
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	☐ Yes
	Describe verification methods and results:	
	Attached supporting documentation: Not applicable	
4.	Operating permit and nitrogen BMP* - Compliance component #4 o	f 5 🛛 Not applicable
Is the system operated under an Operating Permit?		→ or the transfer of the control of
Is the system required to employ a Nitrogen BMP specified in the system design? Yes No If "yes", B below is required to employ a Nitrogen BMP specified in the system design?		f "yes", B below is required
	BMP = Best Management Practice(s) specified in the system design	
	If the answer to both questions is "no", this section does not need to be completed	1.
	Compliance criteria:	
	a. Have the operating permit requirements been met?	
	b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No	
	Describe verification methods and results:	
	Attached supporting documentation: Operating permit (Attach)	