Compliance criteria:			Attached supporting documentation:
System discharges sewage to the ground surface	☐ Yes	⊠ No	☐ Other:
System discharges sewage to drain tile or surface waters.	☐ Yes	⊠ No	
System causes sewage backup into dwelling or establishment.	☐ Yes	⊠ No	
ank integrity – Compliance Compliance criteria:	e comp	onent #2	
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit,	e comp	onent #2 ⊠ №	Attached supporting documentation:   Empty tank(s) viewed by inspector
Compliance criteria: System consists of a seepage pit,		⊠ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  Schlom
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes	⊠ No	Attached supporting documentation:   Empty tank(s) viewed by inspector
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	☐ Yes	⊠ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  Schlom  License number of maintenance business:
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	☐ Yes	⊠ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  07/22/2
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?	☐ Yes	⊠ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  O7/22/2  Existing tank integrity assessment (Attach)  Date of maintenance
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?	☐ Yes	⊠ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attach)  Date of maintenance  (mm/dd/yyyy):  (See form instructions to ensure assessment comp