## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintenance 1/26/22 Re	ason for Maintenance: -	20945 v 2	8194	
Property Address: 15311 - 1929	St.C.t. No- Pr	operty Owner's Name:	Keith Mounch	
Municipality: Still water	State Zip C	ode GEO	Code/Property I.D. #:	
Wiatwasdone others/steme	基本 是 <b>in</b> filed	leasurements (muscabe	completed Heart Color complete	
Tank(s) Pumped		A		di cano
Sludge and scum measured.	Liquid Level of 1	arik in. Sludg	e Level in. Scum Level	in
Do tanks need to be pumped?	Total (Sludge + :	Scum) / Liquid I	and — Michael C	-
No (Il no provide measure	ments)		.evel = % Sludge & Scu	ກ ——
1. Access used to remove septage: Mai			* Tank must be pumped if t	his value
2. If maintenance hole was used, were all co	vers securely replaced?	Yes No please ex	is greater than 25%.	
Explanation:	•			
3. If owner refuses to allow a Subsurface sthem complete and sign the following s	Sewage Treatment Syste	em (SSTS) to be pumped	through the maintenance hole	have
i.	ratement:	(8)		
hole. Lunderstand that removal of colide	(owner's name), refuse to	o allow the removal of so	lids and liquids through the main	tenance
hole. I understand that removal of solids a 4. Is the tank designed as a leaky tank? exam	and liquids through other	access points is not cons	idered maintenance.	
		aryweii, ieacning pit		
Tank#1 Yes No Verificatio Meth	nod Used:		21	
Tank#2 Yes No Verificatio Meth	od Used:			-
5. Is there evidence of tank leakage from a damaged, cracked, or structurally unson	septic, holding, pretrea	tment or pump tank be	low the operating depth or ovid	
. Z	ind maintenance hole co	vers?	and abstraining nebrit of EAlt	ence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☑No	Yes No	Yes No	
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	Yes No	☐ Yes ☐ No	Yes No	
. How many gallons of septage were remo	ved?			
ank#1 //25 Tank#2 / Dg	() Pretreatment Ta	nk PL	mp Tank	
Other information: List any troubleshoot	ing minor ropping sond			
and the second s	mg, minor repairs condi	icted, tank safety conce	rns, or other concerns.	
Certification: Thereby certify as a State of I	Minnesote south desert			
<b>Certification:</b> I hereby certify as a State of I and made the observations,	or directly supervised oth	viaintainer that I personal ers in the performance of	ly conducted the work	
Maintainer's Name: Olson's Sewer Service,		•	Street NE, Forest Lake, MN	
Maintainer's License #: 216 Maintainer	ainer's Phone #: 651-464		anney mily	
Maintainer's Signature	-	Date: 7 -	1/2/)	
- graphy	~	Date	26-22	