DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT 08 6989 28186

Date of Maintenance 7/22/22 Rea	son for Maintenance:	Sin.	5 52010	•
Property Address: 23955 Jawill		operty Owner's Name:	A & Sandry Smith	
Municipality: Twent Calic		ode 55025 GEO		
What was done to the system is	i se jiakiki	leasurements (murche		1) 225
Tank(s) Pumped	Liquid Level of	Tank in cluster		i American
Sludge and scum measured. Do tanks need to be pumped?	Enquia Ecveror	faifk in. Sludg	e Level in. Scum Level	in.
Yes No (If no provide measuren	nents) Total (Sludge +	Scum) / Liquid I	.evel = % Sludge & Scur	n
1. Access used to remove septage: Mair	ntenance Hole Othe	r (Go to #3 below)	* Tank must be pumped if t	his value
2. If maintenance hole was used, were all cov			is greater than 25%. Dlain	
Explanation:	/		,	
3. If owner refuses to allow a Subsurface Sthem complete and sign the following st	ewage Treatment Systement:	em (SSTS) to be pumped	through the maintenance hole	, have
•		o allow the removal of	10.5	
hole. I understand that removal of solids ar	nd liquids through other	access points is not con-	lids and liquids through the maint	enance
4. Is the tank designed as a leaky tank? examp	le: seepage pit, cesspool.	drywell. leachina nit	rdered maintenance.	
Tank#1 Yes No Verificatio Metho		any stan, reaching pil		
Tank#2 Yes No Verificatio Metho				*
5. Is there evidence of tank leakage from a : damaged, cracked, or structurally unsoul	septic, holding, pretrea	ntment or pump tank be	low the operating depth or evid	ence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	☐ Yes D No	Yes Pino	
Septic/Holding Tank #2	Yes No	Yes No	Yes ANO	
Pretreatment Tank	Yes No	☐ Yes ☐ No	Yes No	
Pump Tank	Yes No	Yes Who	T Yes Tillo	
i. How many gallons of septage were remov	red?	-		
Tank#1 (000 Tank#2 1000) Pretreatment Ta		Imp Tank 500	
. Other information: List any troubleshooti	ng, minor repairs cond	ucted, tank safety conce	rns, or other concerns.	
.Certification: I hereby certify as a State of M and made the observations, o	linnesota certified SSTS	Maintainer that I personal	ly conducted the work	-
Maintainer's Name: Olson's Sewer Service, Ir		•	Street NE, Forest Lake, MN	
Maintainer's License #: 216 Maintain	iner's Phone #: 651-464		t	
Maintainer's Signature		Date: 7	77-72	
	N			