	Property Address: 12971 3 rd Street South Afton	
8	Business Name: SS Septic Solutions, LLC.	Date: 7/27/2022
3.	Other compliance conditions – Compliance component #3 of 5	
3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unsecured?		cured?
	☐ Yes ☐ No ☒ Unknown	
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety	/? ☐ Yes ⊠ No ☐ Unknown
	3c. System is non-protective of ground water for other conditions as determined by inspector?	☐ Yes ☐ No
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	☐ Yes No
	Describe verification mathed a sed as a literation	
	Describe verification methods and results:	
	Attached supporting documentation: Not applicable	
4.	Operating permit and nitrogen BMP* - Compliance component #4 of	5 Not applicable
	Is the system operated under an Operating Permit?	"yes", A below is required
Is the system required to employ a Nitrogen BMP specified in the system design? Yes No If "yes", B below is required BMP = Best Management Practice(s) specified in the system design		1000 (C. Saltania Control Cont
	If the answer to both questions is "no", this section does not need to be completed	
	Compliance criteria:	
	a. Have the operating permit requirements been met? ☐ Yes ☐ No	
	b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No	
	Describe verification methods and results:	
	•	
	Attached supporting documentation: Operating permit (Attach)	