## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT

3 -	eason for Maintenance:	2m. h23	36y28347	
11-1/1:		roperty Owner's Name:	Mike Gocker	J *
Municipality:	State NN Zip	Code 558-17 GE	O Code/Property I.D. #:	
What was done to the system?			eomplete Herrica Noticin	Victoria de proprio
Tank(s) Pumped	liquid Laure	_ A		nped).
Sludge and scum measured.  Do tanks need to be pumped?	Liquid Level of	Tarik in. Slud	ge Level in. Scum Lev	el ir
Yes No (If no provide measure	Total (Sludge +	Scum) / Liquid	Level - or er	
1. Access used to remove septage: Ma	aniens)			
		er (Go to #3 below)	<ul> <li>Tank must be pumped is greater than 25%.</li> </ul>	i if this valu
2. If maintenance hole was used, were all co	overs securely replaced?	Yes No please e	explain	
Explanation:	/			
3. If owner refuses to allow a Subsurface s them complete and sign the following s	Sewage Treatment Syst	em (SSTS) to be pumpe	d through the maintenance h	ole, have
l, <u></u>				
hole. I understand that removal of solids a	(Owner's name), refuse	to allow the removal of so	lids and liquids through the m	aintenance
4. Is the tank designed as a leaky tank? example			idered maintenance.	
Tank#1 Yes No Verificatio Meth		алумен, теаспіпд ріт		
Tank#2 Yes No Verificatio Meth	od Used:			
5. Is there evidence of tank leakage from a damaged, cracked, or structurally unsou	contin hatda	atment or pump tank be	low the operating depth are	
Tank		I.	s and actual of 6	vidence of
Septic/Holding Tank #1	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #2	Yes 7 No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	Yes No	Yes No	Yes No	
5. How many gallons of septage were remov		Yes No	Yes No	
Tank #1 (0)				
7000	Pretreatment Ta		Imp Tank	
7. Other information: List any troubleshooti	ng, minor repairs condi	icted, tank safety conce	rns, or other concerns.	
. Certification: I hereby certify as a State of M and made the observations, o	linnesota carifical corre	4.1.4		
and made the observations, o	or directly supervised oth	Maintainer that I personal ers in the performance of	y conducted the work	
Maintainer's Name: Olson's Sewer Service, Ir			Street NE, Forest Lake, MN	
Maintainer's License #: 216 Maintai	ner's Phone #: 651-464		FOREST Lake, MN	
Maintainer's Signature	$\mathcal{T}$			
100 ab C		Date:	26.22	