

OSTP Soil Observation Log

Project ID: v 03.19.15

| | | | |
|---|-------------|--|----------------------|
| Client/ Address: Mark Vestal - 16477 21st Street South | | Legal Description/ GPS: 1402820210100 | |
| Soil parent material(s): (Check all that apply) <input checked="" type="checkbox"/> Outwash <input type="checkbox"/> Lacustrine <input type="checkbox"/> Loess <input type="checkbox"/> Till <input type="checkbox"/> Alluvium <input type="checkbox"/> Bedrock <input type="checkbox"/> Organic Matter | | | |
| Landscape Position: (check one) <input type="checkbox"/> Summit <input type="checkbox"/> Shoulder <input type="checkbox"/> Back/Side Slope <input type="checkbox"/> Foot Slope <input type="checkbox"/> Toe Slope <input type="checkbox"/> Slope shape Linear Linear | | | |
| Vegetation | Grass | Soil survey map units | Elevation: |
| Weather Conditions/Time of Day: Sunny warm 2:00 | | 858 | Date 07/28/22 |
| Observation #/Location: See Map | | Observation Type: Auger | |
| Depth (in) | Texture | Rock Frag. % | Indicator(s) |
| 0-12" | Sandy Loam | <35% | 10YR 4/3 |
| 13" - 33" | Coarse Sand | <35% | 10YR 4/4 |
| 34" - 60" | Sand | <35% | 10YR 4/3 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Comments | | | |
| I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws. | | | |
| Shelley Schlorinka | | 4137 | 7/28/2022 |
| (Designer/Inspector) | | (License #) | (Date) |

Shelley Schlorinka
(Signature)