	Property Address: 16477 21st Street South		
E	Business Name: SS Septic Solutions, LLC.	Date:	07/28/2022
3.	Other compliance conditions – Compliance component #3 of 5		
	3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unsecured?		
	☐ Yes ☐ Unknown		
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety	? 🗌 Yes	☑ No ☐ Unknown
	20 System is non-protection of any state of the state of	Massion resource	
	3c. System is non-protective of ground water for other conditions as determined by inspector?3d. System not abandoned in accordance with Minn. R. 7080.2500?	☐ Yes	⊠ No
	30. System not abandoned in accordance with Minn, R. 7080.2500?	☐ Yes	⊠ No
	Describe verification methods and results:		
	Attached supporting documentation: Not applicable		
1.	Operating permit and nitrogen BMP* - Compliance component #4 of	5 🛭 N	lot applicable
	Is the system operated under an Operating Permit? ☐ Yes ☐ No If "yes", A below is required.		
	Is the system required to employ a Nitrogen BMP specified in the system design? Yes No If "yes", B below is required.		
	BMP = Best Management Practice(s) specified in the system design		7
	If the answer to both questions is "no", this section does not need to be completed.		
	Compliance criteria:		
	a. Have the operating permit requirements been met?		
	b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No		
	Describe verification methods and results:		
	٠		
	Attached supporting documentation: Operating permit (Attach)		
	G sporting point (Attach)		