pact on public health – C	omplia	nce com		
Compliance criteria:			Attached supporting documentation:	
System discharges sewage to the ground surface	☐ Yes	⊠ No	☐ Other: ☐ Not applicable	
System discharges sewage to drain tile or surface waters.	☐ Yes	⊠ No	az	
System causes sewage backup into dwelling or establishment.	☐ Yes	⊠ No		
Describe verification methods and	l results:		-	
nk integrity – Compliance Compliance criteria:	comp	onent #2		
Compliance criteria: System consists of a seepage pit,	e compo	onent #2 ⊠ No	of 5  Attached supporting documentation:  ⊠ Empty tank(s) viewed by inspector	
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit,	1		Attached supporting documentation:  ⊠ Empty tank(s) viewed by inspector	Mevers
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	1	⊠ No	Attached supporting documentation:	Meyers:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes	⊠ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:	
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	☐ Yes	⊠ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business	7/28/202
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?	☐ Yes	⊠ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business  Date of maintenance:  Existing tank integrity assessment (Attach	7/28/202 n)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	☐ Yes	⊠ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business  Date of maintenance:  Existing tank integrity assessment (Attach  Date of maintenance (mm/dd/yyyy):  (must be within	7/28/202 n) three year
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?	☐ Yes	⊠ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business  Date of maintenance:  Existing tank integrity assessment (Attach  Date of maintenance (mm/dd/yyyy): (must be within	7/28/202 1) three year ent compli