DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT (2200W 28354

Date of Maintenance 7/28/22 Re	eason for Maintenance:			
Property Address: 9700 2041	h Stu P	roperty Owner's Name:	George + Marilya A	V- 11-00
Municipality: Forest Lake	State Mr Zip	- 0	O Code/Property I.D. #:	<u> </u>
What was done to the system is	4		រល់ប្រព្រះ ម៉ូស្រែក នៃស្រីស្រួស មួយ មិន មួយ	对
Tank(s) Pumped	liquidi	- A		
Sludge and scum measured.	Liquid Level of	Tarik in. Slud	ge Level in. Scum Level	in.
Do tanks need to be pumped? Yes No (If no provide measure	Total (Sludge +	Scum) / Liquid	level = % Studen 8.5	
	ments)			
1. Access used to remove septage: Ma	intenance Hole Oth	er (Go to #3 below)	 Tank must be pumped if is greater than 25%. 	this value
2. If maintenance hole was used, were all co	vers securely replaced?	Yes No please e	xplain	
Explanation:				
3. If owner refuses to allow a Subsurface s them complete and sign the following s	Sewage Treatment Syst	em (SSTS) to be pumpe	d through the maintenance hol	
	itatement:		and manufacture ito	e, nave
l,	(owner's name), refuse	to allow the removal of so	lids and liquids through the mair	itenance
hole. I understand that removal of solids a	ind liquids through othe	access points is not con-	idered maintenance.	er inite
4. Is the tank designed as a leaky tank? example		drywell, leaching pit		
Tank#1 Yes No Verificatio Meth	od Used: Uisual			
Tank#2 🔲 Yes 🔎 No Verificatio Meth	od Used: Visual			
5. Is there evidence of tank leakage from a	sentic holding protect	emant as muma and t		
damaged, cracked, or structurally unsou	nd maintenance hole c	overs?	low the operating depth or evi	dence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ♠No	Yes No	☐ Yes ♠ No	
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	Yes HNo	Yes INO	Yes No	
6. How many gallons of septage were remove	ved?			
Tank#1 1250 Tank#2	Pretreatment Ta	nk PL	imp Tank 1.50	
7. Other information: List any troubleshooti	ng, minor repairs cond			
			rns, or other concerns.	
8. Certification: I hereby certify as a State of N	Ninnesota certified SSTS I	Maintainer that I personal	han dia dia	
and made the observations, o	or directly supervised oth	ers in the performance of	this job.	
Maintainer's Name: Olson's Sewer Service, in	nc. Maintaine	r's Address: 17638 Lyons	Street NE, Forest Lake, MN	
Maintainer's License #: 216 Maintai	iner's Phone #: 651-464		, orest Lake, Mily	
Maintainer's Signature	6	Date: 7/	120 177	9
1			- 0/00	