DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 122 Reason for Maintenance: 41255 w 28350				
Property Address: 14269 5TO	roix TRN Pro	operty Owner's Name:	ray Loa Nel	son
Municipality: St. // water	State Zip Co		Code/Property I.D. #:	
What was done to the system? Tank(s) Pumped	r Projectivity	easurements (musco e)	ompleted franksiNoTujui	
Sludge and scum measured.	Liquid Level of T	afik in. Sludge	e Level in. Scum Lev	/elin.
Do tanks need to be pumped? Yes No (If no provide measuren	nents) Total (Sludge + S	icum) / Liquid L	evel = % Sludge &	Scum
1. Access used to remove septage: Main	tenance Hole Othe	r (Go to #3 below)	* Tank must be pumpe	d if this value
2. If maintenance hole was used, were all cov	ers securely replaced?	Yes No please exp	is greater than 25%. Diain	
Explanation:	•			
3. If owner refuses to allow a Subsurface So them complete and sign the following st	ewage Treatment Syste atement:	em (SSTS) to be pumped	through the maintenance	hole, have
(owner's name), refuse to allow the removal of solids and liquids through the maintenance hole. I understand that removal of solids and liquids through other access points is not considered maintenance.				
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit				
, <u>,</u>		arywen, reactning pit		
Tank#1 Yes No Verificatio Metho	od Usea:			G .
Tank#2 Yes No Verificatio Metho	od Used:			
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?				
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	Yes No	Yes No	
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	☐ Yes ☐ No	
Pump Tank	Yes No	Yes Wo	☐ Yes ♠No	
i. How many gallons of septage were remov	red?			
Tank #1 100 Tank #2 Pretreatment Tank Pump Tank 250				
 Other information: List any troubleshooti 	ng, minor repairs cond	ucted, tank safety conce	rns, or other concerns.	
. Certification: I hereby certify as a State of N and made the observations, o	Ainnesota certified SSTS or directly supervised other	Maintainer that I personal Mers in the performance of	ly conducted the work	
Maintainer's Name: Olson's Sewer Service, I	nc. Maintaine	r's Address: 17638 Lyons	Street NE, Forest Lake, MN	
Maintainer's License #: 216 Maintainer's Phone #: 651-464-2082				
Maintainer's Signature	7	Date: 7	-27-22	