

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in	n its entirety to co	onstitute a valid m	naintenance per	rmit. This permit n	nust be completed
prior to performing mainte	nance activities a	nd remain on-site	for the duration	on of the maintena	nce activity.
Date of Maintenance: 1-27-	Reason for M	Naintenance: K	eg Mai	47	_
Property Address: 12895	Ozark.	Fr VPrope	rty Owner's Nan	ne: David	Barnun
Municipality: Stillnater	ZIR:35080	Property Identific	cation Number: _		
Maintenance Permit No: 5598n	AND Mainta	ainer Name and Lic	ense No Smilie	's Sewer Service / I	2428
Maintenance Permit No. 1887 No. 1887 Maintainer Name and License No. Smilie's Sewer Service / L 2428					
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
Yes No (if no provide n	neasurements) =	% Sludge & Scum	Tar	n <u>ks must be pumpe</u>	dif 25% or greater
1. Access used to remove septage	: Maintenance H	loleother (ente	r authorization co	de)	
2. Were all covers securely replac	ed? Yes No)			
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or					
evidence of damaged, cracked, or structurally unsound maintenance hole covers? YesNO					
Tank Leaking Out Leaking In Cover Damage					
		1	1/	Cover Dalliage	
Septic/Holdin	g Tank #1	Yes No _	Yes No	Yes No	
Septic/Holdin	g Tank #2	Yes No	Yes No	Yes No	
Pretreatment	Tank	Yes No	Yes No	Yes No	
Pump Tank		Yes No	Yes No	Yes No	
4. How many gallons of septage were removed?					
Tank #1 <u>/30 0</u> gal Tank	#2gal	Pretreatment tan	kgal	Pump Tank	gal
5. Other information: List any tro	ubleshooting, mir	or repairs conduc	ted, tank safety	y concerns, or othe	er concerns.
	10/	<i>X</i> . /			
6. Location of septage disposal: _	Land	Apply	-		
	S	milie's Sewer Serv P.O. Box 100 Scandia, MN 5507			
	P: 651-433	-3934 License Nu			
Maintenance	activities must	be reported to t	he Departmen	t within 90 days.	
White Copy-N	Naintainer submits to	o Washington County	/ Pink Copy-Prop	erty Owner Record	