## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT

Date of Maintenance 8-5	- 22 Reason for Mo	intenance: A	\ 0(0)2		
			98819		
	Quarry 1	Ale Proper	ty Owner's Name	Leda Benecht	•
Municipality: <u>Scurd</u> : a	State	Zip Code	<u> </u>	GEO Code/Property I.D. #:	
A Za What was done to the	s siem g	a Jank Mens	urements (must	ice somplex effect of the original	
Tank(s) Pumped		and the second			
Siudge and scum measured.	H	uid Level of Tarik	in. SI	udge Level in. Scum Level	in
Do tanks need to be pumped  Yes No (If no provid	? e measurements)    To	tal (Sludge + Scum	n) / Liqu	iid Level = % Sludge & Sc	um
1. Access used to remove septage		ole [Other (Go	to #3 below)	* Tank must be pumped i	f this value
2. If maintenance hole was used,	vere all covers secure	ly replaced? ∕⊠iγ	es TNo pleas		
Explanation:		****	I To breasi	: Ехрин	
3. If owner refuses to allow a Sul them complete and sign the fo	osurface Sewage Tre	atmont Suctom (C	CTC) An ha		
them complete and sign the fo	llowing statement:	Jystein (3	o be pum	ped through the maintenance ho	le, have
l,	(owner's na	me), refuse to allo	w the removal of	solids and liquids through the mai	
hole. I understand that removal	of solids and liquids t	hrough other acce	ss points is not co	onids and injures through the mai	ntenance
4. Is the tank designed as a leaky ta	nk? example: seepage	pit, cesspool, drywe	ell, leaching pit	onsidered maintenance.	
/	atio Method Used:				
Tank#2 ☐ Yes ☑ No Verific	atio Method Used:				
- The second		40			
<ol><li>Is there evidence of tank leakage damaged, cracked, or structura</li></ol>	lly unsound mainter	aing, pretreatmer lance hoie covers	nt or pump tank ?	below the operating depth or ev	idence of
Tank	1	ng Out	Leaking In	Cover Damage	
Septic/Holding T		No	Yes No	Yes TNo	
Septic/Holding Ta	ank #2 Yes	[⊀No	Yes No	Yes No	
Pretreatment Tan	k Yes		Yes No	☐ Yes ☐ No	
Pump Tank		□ No	Yes No	Yes No	
6. How many gallons of septage w	ere removed?			Sandra Sandra Fred	
Tank#1 Doc Tank#2	(200 Pre	treatment Tank		Pump Tank	
7. Other information: List any trou	bleshooting, minor r	 epairs conducted	tank safatu sa		
		-5	, cally salety (O)	icerns, or other concerns.	
8. Certification: I hereby certify as a	State of Minnesota co	ertified SSTS Mainta	ainer that I nerso	nathy conducted the	
and made the obse	rvations, or directly su	pervised others in	the performance	of this job.	
Maintainer's Name: Olson's Sewer					
	Service, Inc.	Maintainer's Add	dress: 17638 Lyo	ns Street NE, Forest Lake, MN	
Maintainer's License #: 216	Service, Inc.  Maintainer's Phone		-	ns Street NE, Forest Lake, MN	
				ns Street NE, Forest Lake, MN	