DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Mair		eason for Maintenance:	puzy123	3174	
Property Add	dress: 7175-125th	St. W. Linux PI	operty Owner's Name:	Janes March	_
Municipality:	Hazo			Code/Property I.D. #:	<u> </u>
A ZWn	(tvas/one to thesys) (mig	Fig. 19		sompleted if tanks No repun	
Tank(s) Pu	mped	11		completed if canks No Figur	(ped)
Sludge an	d scum measured.	Liquid Level of 1	faritk in. Sludg	e Level in. Scum Leve	e l in
	need to be pumped?	Total (Sludge + :			
V	No (If no provide measure	anents)		evel = % Sludge & S	Scum
1. Access used	to remove septage: 5/1/1a	intenance Hole 🔲 Othe	r (Go to #3 below)	* Tank must be pumped	if this value
2. If maintenar	nce hole was used, were all co	overs securely replaced?	Yes No please ex	is greater than 25%.	
Explanation:			is in pieuse ex	piain	
3. If owner refe them compl	uses to allow a Subsurface : ete and sign the following :	Sewage Treatment Syste	m (SSTS) to be pumped	through the maintenance h	ole, have
l,	and organizate following s		*		
	stand that removed of self-t-	(owner's name), refuse to	allow the removal of sol	ids and liquids through the m	aintenance
4. Is the tank de	stand that removal of solids a	ind liquids through other	access points is not consi	dered maintenance.	
	signed as a leaky tank? exam		frywell, leaching pit		
Tank#1	es No Verificatio Meth	od Used:			
Tank#2 🔲 Y	es ZINo Verificatio Meth	od Used:			
5. Is there evide	ence of tank leakage from a	Sentic holding protect	tment or pump tank bel	ow the operating depth or a	vido o of
	cked, or structurally unsou Tank	1	Y C. J.	a second debattot e	ardetice of
	Septic/Holding Tank #1	Leaking Out	Leaking In	Cover Damage	
		Yes No	☐ Yes No	☐ Yes ☐ No	
	Septic/Holding Tank #2	Yes No	Yes No	Yes No	
	Pretreatment Tank	Yes No	Yes No	Yes No	
S Manner	Pump Tank	Yes No	Yes No	☐ Yes ☐ No	
o. now many gal	lions of septage were remo	ved?			
Tank#1 156	V Tank#2 60	Pretreatment Tar	7 641	np Tank	
7. Other informa	tion: List any troubleshooti	ng, minor repairs condu	cted, tank safety concer	ns, or other concerns.	
8. Certification:	I hereby certify as a State of N	Ninnesota certified SSTS M	aintainer that I personally	Conducted the work	
	the observations, c	an ectivisupervised office	rs in the performance of t	his job.	
Maintainer's Na	me: Olson's Sewer Service, I	nc. Maintainer'	s Address: 17638 Lyons S	treet NE, Forest Lake, MN	
Maintainer's Lice	ense #: 216 Mainta	iner's Phone #: 651-464-			
Maintainer's Sig	nature A	W	Date: Sr	82	
		/	V	V	