	roperty Address: 2025 QUEENS AVE S, CITY OF LAKE ST CROIX BEACH			
В	iness Name: SS Septic Solutions, LLC.		Date: 8/3/2022	
3.	Other compliance conditions – Compliance component #3 of 5			
	3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unsecured?			
	☐ Yes ☑ No ☐ Unknown			
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety	? 🗌 Yes	No □ Unknown	
	3c. System is non-protective of ground water for other conditions as determined by inspector?	☐ Yes	⊠ No	
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	☐ Yes	⊠ No	
	Describe verification methods and results:			
	Attached supporting documentation: Not applicable			
4.	Operating permit and nitrogen BMP* – Compliance component #4 of	5 × 1	Not applicable	
	Is the system operated under an Operating Permit?	"ves". A	below is required	
	Is the system required to employ a Nitrogen BMP specified in the system design? Yes No If			
	BMP = Best Management Practice(s) specified in the system design	, ,-		
	If the answer to both questions is "no", this section does not need to be completed.			
	Compliance criteria:			
	a. Have the operating permit requirements been met?			
	b. Is the required nitrogen BMP in place and properly functioning? Yes No			
	Describe verification methods and results:			
	Attached supporting documentation: Operating permit (Attach)			