	roperty Address: 6166 Jarvis Ave. N. Grant Twp				
В	Business Name: SS Septic Solutions, LLC		Date: 8/10/2022		
3.	Other compliance conditions – Compliance component #3 of 5	W 100 D 30 T			
3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unsecured?					
	☐ Yes ☐ No ☒ Unknown				
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safet	y? 🗌 Yes	⊠ No ☐ Unknown		
	3c. System is non-protective of ground water for other conditions as determined by inspector?	☐ Yes	⊠ No		
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	☐ Yes	⊠ No		
	*				
	Describe verification methods and results:				
	Attached supporting documentation: Not applicable				
			13.02 (M.1.2.02)		
4.	Operating permit and nitrogen BMP* - Compliance component #4 of	of 5 ⊠ı	Not applicable		
107.000	en militare rende di la comunicazione de la comunicazione de la comunicazione de la comunicazione del del comunicazione del comunicazione				
			below is required		
	Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No	If "yes", B	below is required	1	
	BMP = Best Management Practice(s) specified in the system design				
	If the answer to both questions is "no", this section does not need to be completed	d.			
	Compliance criteria:				
	a. Have the operating permit requirements been met? ☐ Yes ☐ No				
	b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No				
	Describe verification methods and results:				
	Attached supporting documentation: Operating permit (Attach)				