DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Main	tenance 8 Nu ZZ Re	ason for Maintenance:	# c5400h	28382	
	1240-530 j	St. Pi	operty Owner's Name		
A CONTROL OF THE CONT	Sembla	State MN Zip C	ode <u>55073</u> GEO	Code/Property I.D. #:	6
And the same of the same of	t was done to the system?	A Republika	leasurements (mustese	ល្បាញ់ផ្ទៃ វីស្រាវ៉ូនែលិស្សាវ៉ា	ed S
Tank(s) Pu	•	liquid and of	A.		
	scum measured.	Liquid Level of	Taiffk in. Sludg	je Level in. Scum Level	in
	eed to be pumped? No (If no provide measure)	ments) Total (Sludge +	Scum) / Liquid	_evel = %Sludge & Sc	um
	to remove septage:		er (Go to #3 below)	* Tank must be pumped i	f this value
2. If maintenan	ce hole was used, were all co	vers securely replaced?	Yes No please ex		
Explanation:			•	•	
3. If owner refu them comple	uses to allow a Subsurface S ete and sign the following s	ewage Treatment Systotatement:	em (SSTS) to be pumped	through the maintenance ho	le, have
1,		(OWDer's name) refuse +	a allow the remaint of	N. 4	
hole. Lunders	stand that removal of solids a	nd liquids through other	access points is not cons	ids and liquids through the mai	ntenance
4. Is the tank de	signed as a leaky tank? exam	ple: seepage pit, cesspool.	drywell. leachina nit	dered maintenance.	
Tank#1 XX	es No Verificatio Meth	od Used: Sucal	,,		
	es No Verificatio Meth				4
damaged, cra	cked, or structurally unsou	septic, holding, pretrea nd maintenance hole co	itment or pump tank be	low the operating depth or ev	idence of
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes No	☐ Yes ☑ No		
	Septic/Holding Tank #2	☐Yes ☐No	Yes No	Yes No	
	Pretreatment Tank	Yes No	Yes No	Yes No	
	Pump Tank	☐Yes ☐No	Yes No	Yes No	
6. How many gal	lons of septage were remov		Lies Litto	Yes No	
Tank#1 550	Tank #2 Pretreatment Tank Pump Tank				
7. Other information	tion: List any troubleshooti	ng, minor repairs condu			
			entral entire parety conice	is, of other concerns.	
8. Certification:	I hereby certify as a State of N and made the observations, o	Minnesota certified SSTS Nor directly supervised or h	Maintainer that I personall	y conducted the work	
	me: Olson's Sewer Service, I			tnis Job. Street NE, Forest Lake, MN	
Maintainer's Lice	ense #: 216 Mainta	iner's Phone #: 651-464		r	
Maintainer's Sig	nature MM		Date: 8/	16/25	
				100	