DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance Rea	ason for Maintenance:	20460c 29	182	
Property Address: 23880 mno	yan Av. Pr	operty Owner's Name:	Brian Crooker	
Municipality: Chia-Ct	State Zip C	ode GEC	Code/Property I.D. #:	
What was done to the spatime.	# Electricity	dersyrciáchás (mystebe	डव्याची वस्तु में हिल्ला है जो ह	
Tank(s) Pumped		A.		dis
Sludge and scum measured.	Liquid Level of	arik in. Slude	je Level in. Scum Level	in.
Do tanks need to be pumped?	Total (Słudge +	Scum) / Liquid	- 0/ Shidan 0.5	
Yes No (If no provide measurer	ments)	- Liquid	Level = % Sludge & Scum	
1. Access used to remove septage: Main	ntenance Hole []Othe	r (Go to #3 below)	* Tank must be pumped if this v	alue
2. If maintenance hole was used, were all co	vers securely replaced?	Yes No please ex	is greater than 25%. Plain	
Explanation:	•	`		
3. If owner refuses to allow a Subsurface S them complete and sign the following s	ewage Treatment Systetatement:	em (SSTS) to be pumped	I through the maintenance hole, hav	— 'e
l				
hole. I understand that removal of solids a	(Owner's name), refuse t	o allow the removal of so	lids and liquids through the maintenar	ıce
hole. I understand that removal of solids a 4. Is the tank designed as a leaky tank? examp	na nquias through other	access points is not cons	idered maintenance.	
/		aryweii, ieacning pit		
Tank#1 Yes X No Verificatio Meth	od Used:		9	
Tank#2 Yes No Verificatio Meth	od Used:			_
5. Is there evidence of tank leakage from a	septic, holding, pretre	itment or numn tank he	low the executive stance.	_
damaged, cracked, or structurally unsou	nd maintenance hole co	overs?	iow the operating depth or evidence	e of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	Yes No	Yes INO	
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	Yes No	Yes No	Yes No	
. How many gallons of septage were remove	ved?			
ank#1 / 000 Tank#2 / ()7	77 / Pretreatment Ta	-l		
100			ımp Tank —————	
. Other information: List any troubleshooti	ng, minor repairs cond	acted, tank safety conce	rns, or other concerns.	
Certification: I hereby certify as a State of A and made the observations, o	Ainnesota certified SSTS I	Maintainer that I personal	ly conducted the work	-
Maintainer's Name: Olson's Sewer Service, I		-	Street NE, Forest Lake, MN	
Maintainer's License #: 216 Mainta	iner's Phone #: 651-464		1	-
Maintainer's Signature	1	Date: 💸	-22-22	
7 19	7	-		