House

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT

Date of Maintenance 8 24 24 22 Rea	son for Maintenance:	a77256	28590	
Property Address: 22200 Mus	Pro Sandwal	perty Owner's Name:	Syd Stephan	,
Municipality: Scanding	State Zip Co	de <u>5508</u> GEO	Code/Property I.D. #:	
What was done to the system?	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	erinentalistimistese	somplete like nikin Open mije	)是汉生
Jank(s) Pumped	Liquid Level of Ta	arik in. Sludg	ge Level in. Scum Level	in.
Sludge and scum measured.  Do tanks need to be pumped?		III. Studi	le resel 2cam resel	in. 
Yes No (If no provide measurer	nents) Total (Sludge + S	cum)/ Liquid l	Level = % Sludge & Scur	n
1. Access used to remove septage: Mair	ntenance Hole Other	(Go to #3 below)	* Tank must be pumped if t	nis value
2. If maintenance hole was used, were all cov	vers securely replaced?	Yes No please ex	is greater than 25%. <b>Plain</b>	
Explanation:				
3. If owner refuses to allow a Subsurface S them complete and sign the following st	ewage Treatment Systemater in the system of	m (SSTS) to be pumped	through the maintenance hole	have
1,	(owner's name), refuse to	allow the removal of so	lids and liquids through the maint	
hole. I understand that removal of solids a	nd liquids through other a	access points is not cons	iidas and iiquids tillough the maint idered maintenance	enance
4. Is the tank designed as a leaky tank? examp				
Tank#1 Yes No Verificatio Metho	od Used:			
Tank#2 Yes No Verificatio Metho	od Used:			2
<ol><li>Is there evidence of tank leakage from a damaged, cracked, or structurally unsoul</li></ol>	septic, holding, pretreat nd maintenance hole co	ment or pump tank be vers?	low the operating depth or evid	ence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes △N6	Yes No	Yes Ho	
Septic/Holding Tank #2	Yes No	Yes Wo	Yes HNo	
Pretreatment Tank	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	
Pump Tank	Yes No	Yes No	☐ Yes ☐ No	
5. How many gallons of septage were remov	ved?			
Fank #1 Tank #2 Pretreatment Tank Pump Tank				
7. Other information: List any troubleshooti	ng, minor repairs condu	cted, tank safety conce	erns, or other concerns.	
Certification: I hereby certify as a State of A and made the observations, c	Minnesota certified SSTS Nor directly supervised other	laintainer that I persona ers in the performance o	lly conducted the work f this job.	
Maintainer's Name: Olson's Sewer Service, I	nc. Maintainer	's Address: 17638 Lyons	Street NE, Forest Lake, MN	
Maintainer's License #: 216 Mainta	iner's Phone #: 651-464	2082	,	
Maintainer's Signature		Date: 8	24/22	