DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 8 25 22 Rea	son for Maintenance:	97	44962859	V
Property Address: David Hud	slik Pi	operty Owner's Name	23920 A	A snartter
Municipality: 7 Not Jake	State Zip C	ode	GEO Code/Property I.D.	#:
What was done to the system?	and the state of t	der stüren en ekimisis	desomplex discovis	Morramoods 2
Tank(s) Pumped	lieuidi evel ef	- A.		
Sludge and scum measured.	Liquid Level of	iank in. S	ludge Level in.	Scum Level in.
Do tanks need to be pumped? Yes No (If no provide measure)	Total (Sludge +	Scum) / Liqu	uid Level = %	Sludge & Scum
1. Access used to remove septage:			is greater th	e pumped if this value an 25%.
2. If maintenance hole was used, were all cov	vers securely replaced?	Wes No pleas	e explain	
Explanation:				
3. If owner refuses to allow a Subsurface S them complete and sign the following st	ewage Treatment Systlatement:	em (SSTS) to be pum	ped through the main	tenance hole, have
t, ·	(OWDER's name) refuse t	a allow the removal o	fealide and limite at	4.4
l, (owner's name), refuse to allow the removal of solids and liquids through the maintenance hole. I understand that removal of solids and liquids through other access points is not considered maintenance.				
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit				
Tank#1 Yes No Verificatio Metho		,		
Tank#2 Yes No Verificatio Metho	-			· ·
		tmont or name tool	chalamaha amamat	
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?				
Tank	Leaking Out	Leaking In	Cover Damag	e
Septic/Holding Tank #1	Yes Wo	Yes No	☐ Yes Who	
Septic/Holding Tank #2	Yes No	Yes No	Yes Two),
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	Yes No	Yes No	Yes No)
6. How many gallons of septage were remove	ved?			
Tank#1 () Tank#2	Pretreatment Ta	nk	Pump Tank	
7. Other information: List any trouble hosti				
7. Other information: List any troubleshooti	ng, minor repairs cond	ucted, tank safety co	ncerns, or other conce	rns.
R Cartification. I haraby cartify as a State of t	Ainneath and Colore			
8. Certification: I hereby certify as a State of N and made the observations, or	or directly supervised ot	Maintainer that i persiners in the performant	onally conducted the wo	ork
Maintainer's Name: Olson's Sewer Service, I			ons Street NE, Forest La	ka 84bi
			Ons Street ME, FOREST Lai	Ke, MIN
Maintainer's License #: 216 Mainta	iner's Phone #: 651-46	4-2082		•
Maintainer's Signature	lon	Date:	8-25-22	
	9			