

OSTP Soil Observation Log

Project ID:

v 03.19.15



Client/ Address: 195 Quinlan Ave. N.

Legal Description/ GPS:

3502920430038

Soil parent material(s): (Check all that apply)

- Outwash
- Lacustrine
- Loess
- Till
- Alluvium
- Bedrock
- Organic Matter

Landscape Position: (check one)

- Summit
- Shoulder
- Back/Side Slope
- Foot Slope
- Toe Slope

Slope shape

Linear Linear

Vegetation

Lawn

Soil survey map units

858

Slope%

Elevation:

Weather Conditions/Time of Day:

Sunny warm 3:00

Date

08/26/22

Observation #/Location:

See Map

Observation Type:

Auger

Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Structure		
							Shape	Grade	Consistence
0 - 6"	Loamy Sand	<35%					Granular	Weak	Loose
7" - 28"	Sandy Loam	<35%					Granular	Weak	Loose
29" - 60"	Coarse Sand	<35%					Granular	Weak	Loose

Comments

This property is on the edge of a gravel pit. It has nice loam - sand soil but also gravel.

I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.

Shelley Schlonka

4137

8/26/2022

(Designer/Inspector)

(Signature)

(License #)

(Date)