



Client / Address: Marsha Shotley - 13928 21st Street N.		Legal Description / GPS: 2002920440012	
Soil parent material(s): (Check all that apply)			
<input type="checkbox"/> Outwash <input type="checkbox"/> Lacustrine <input type="checkbox"/> Loess <input checked="" type="checkbox"/> Till <input type="checkbox"/> Alluvium <input type="checkbox"/> Bedrock <input type="checkbox"/> Organic Matter			
Landscape Position: (check one)			
<input type="checkbox"/> Summit <input checked="" type="checkbox"/> Shoulder <input type="checkbox"/> Back/Side Slope <input type="checkbox"/> Foot Slope <input type="checkbox"/> Toe Slope <input type="checkbox"/> Slope shape Convex Convex			
Vegetation	Lawn	Soil survey map units 342C	Elevation:
Weather Conditions/Time of Day:		Date	
Warm sunny 3:00 pm		08/30/22	
Observation #/Location:		Observation Type:	
See Map		Auger	
Depth (in)	Texture	Matrix Color(s)	Indicator(s)
0-12"	Sandy Loam	7.5YR 3/4	Shape Granular Grade Weak Consistence Loose
Comments: Hit obstruction at 12" on several borings. Pit will need to be dug to verify soils on new system.			
I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.			
Shelley Schломka (Designer/Inspector)		4137 (License #)	
		8/30/2022 (Date)	