

OSTP Soil Observation Log



Project ID: v 03.19.15

Client / Address:		David Winegar - 910 Mark Ave N		Legal Description / GPS:		3102920220004	
Soil parent material(s): (Check all that apply)							
<input type="checkbox"/> Summit		<input checked="" type="checkbox"/> Shoulder		<input type="checkbox"/> Back/Side Slope		<input type="checkbox"/> Loess	
<input type="checkbox"/> Outwash		<input type="checkbox"/> Lacustrine		<input type="checkbox"/> Till		<input type="checkbox"/> Alluvium	
<input type="checkbox"/> Bedrock		<input type="checkbox"/> Organic Matter					
Landscape Position: (check one)				Slope shape			
<input checked="" type="checkbox"/> Lawn		<input type="checkbox"/> Toe Slope		<input type="checkbox"/> Convex		<input type="checkbox"/> Convex	
Vegetation		Soil survey map units 49B & 454C		Elevation:			
Weather Conditions/Time of Day:				Date		09/01/22	
Warm sunny 10:30 am							
Observation #/Location:				Observation Type: Auger			
See Map							
Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Structure
0-6"	Loamy Sand	<35%	10YR 4/3				----- Structure-----
7" - 31"	Sand	<35%	10YR 4/4				Grade Consistence
32" - 65"	Coarse Sand	<35%	10YR 4/4				
Comments							
I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.							
Shelley Schloimka		4137		9/1/2022			
(Designer / Inspector)		(License #)		(Date)			

Shelley Schloimka
(Signature)