DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

9/8/22

SSTS MAINTENANCE REPORT

Pate of Maintenance Re	ason for Maintenance:	67936e2	8585	
Property Address: 18233	roust Ar. P	roperty Owner's Name:	Tim KuhL	
Municipality:	State/WN Zip C	Geode 550% GEO	Code/Property I.D. #:	·
What was done to the system.	4.45(1167)	liggi offering hiji tope	្តា ស្រីសង្គមាន មាន មាន ស្រីសាលា ព	um brails & st
☐ Tank(s) Pumped		Α.		
Sludge and scum measured.	Liquid Level of	Taifik in. Sludi	ge Level in. Scum l	Level in
Do tanks need to be pumped? Yes No (If no provide measure	Total (Sludge +	Scum) / Liquid	level = % Chida	. 0. C
	ments)	- Idela		
\sim		er (Go to #3 below)	* Tank must be pum is greater than 25%	ped if this value
2. If maintenance hole was used, were all co	vers securely replaced? \	Pes □No please e		o .
Explanation:	1	(
3. If owner refuses to allow a Subsurface S	ewage Treatment Syst	em (SSTS) to be pumper	through the maintenance	tahala kuu
them complete and sign the following s	tatement:	(6)	ang the mantenant	re noie, Nave
l,	(owner's name), refuse t	o allow the removal of so	lids and liquids through the	O Po Dintonos es
hole. I understand that removal of solids a	nd liquids through other	access points is not cons	idered maintenance.	e maintenance
4. Is the tank designed as a leaky tank? example	ple: seepage pit, cesspool,	drywell, leaching pit		
Tank#1 Yes 7No Verificatio Meth	od Used:			
<i>D</i>	<i>‡</i> ———			***************************************
(
Is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretrei nd maintenance hole c	ntment or pump tank be	low the operating depth	or evidence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	TYes TNO		_
Septic/Holding Tank #2	☐Yes ☐No	Yes No		
Pretreatment Tank	Yes No	Yes No	_	-
Pump Tank	Yes No	☐ Yes ☑ No	Yes No	-
6. How many gallons of septage were removed	ved?	0	Life III	-
Tank #1 (257) Tank #2	Pretreatment Ta	nk n.	20	
			Imp Tank 350	
7. Other information: List any troubleshooti	ng, minor repairs cond	ucted, tank safety conce	rns, or other concerns.	
2 Contilientions I have been self.				
8. Certification: I hereby certify as a State of A and made the observations, of	Ainnesota certified SSTS I or directly supervised oth	Maintainer that I personal ers in the performance of	ly conducted the work this job.	
Maintainer's Name: Olson's Sewer Service, I	nc. Maintaine	r's Address: 17638 Lyons	Street NE, Forest Lake, MN	
Maintainer's License #: 216 Mainta	iner's Phone #: 651-464		(
	7	(7	(400	
Maintainer's Signature	<i>U</i>	Date:	1-8-did	