

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance	9/13/22	_ Reason for N	laintenance:	Routi	ne	
Property Address:	10880 Kingsboroug	h Ct S. Cottag	ge Grove	Property Owner	's Name:	Corey Schuler
Municipality:		ZIP: <u>55016</u>	Property Id	entification Num	iber:	
Maintenance Permit No:		Mainta	Maintainer Name and License No.		Schlomka Service LLC/L2989	

Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)				
 Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped? Yes No (if no provide measurements) 	Liquid Level of Tank in Sludge Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater				

1. Access used to remove septage:
Maintenance Hole Other (enter authorization code)

- 2. Were all covers securely replaced? Tes No N/A
- 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? <u>No couldn't confirm precast vis</u> No - couldn't confirm precast via camera

Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Some answers un	Ves No known. Pumped thro	Yes No-	
Septic/Holding Tank #2	- I Yes I No	Yes - No	- Yes No-	
Pretreatment Tank	□ Yes □No	□ Yes □No	□ Yes □No	
Pump Tank	🗆 Yes 🗌 No	□ Yes □No	□ Yes □No	

4. How many gallons of septage were removed?

1000 gal Pretreatment tank_____ gal Pump Tank _____ gal Tank #1 1000 gal Tank #2

5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.

Some answers unknown. Pumped through inspection pipe.

Location of septage disposal: Metro MCES WWTP

Schlomka Services, LLC 1904 Vermillion St. Hastings, MN 55033 License# 2989 P: 651-459-3718

Maintenance activities must be reported to the Department within 90 days.