Property address: 7499 Grandcla Be City: Cottage Grave	State: NN Parcel ID: Zip code: 55016
Optional section: Sewage Tank Compliance Certification	
This form does not represent a complete system inspection	No. 2 de la companya
Instructions: This section of the form may be completed and signal Maintenance Business who personally conducts the necessary pathe system.	report and only certifies sewage tank compliance status.  gned by a Designated Certified Individual (DCI) of a licensed SSTS rocedures to assess the compliance status of each sewage tank in
When this section of the form is signed by a qualified certified pro Existing System Compliance Inspection Report: Compliance have found on the MPCA website at https://www.pca.state.ne.us/	ofessional, it becomes necessary supporting documentation to an ection form - Existing system (we wwists 4-31b). This form can be
individual other than the SSTS Inspector that submits the inspector component compliance and is allowable under Minn. R. 7082.070 three years beyond the signature date on this form unless a new exequired according to local regulations. Additional Administrative R. 7082.0700, subp. 4 Items B, C, and D; 7083.0730 Item C.	when existing septic tank compliance status is determined by an on report. It represents a third party assessment of SSTS
⊠ Certificate of sewage tank compliance	
Affirm all three statements:	☐ Notice of sewage tank non-compliance Select all that apply:
<ul> <li>☑ The SSTS does not contain a seepage pit, cesspool, drywell, leaching pit, or other pit.</li> <li>☑ It does not contain a sewage tank that was designed to be watertight, but subsequently leaks below the designed operating depth.</li> <li>☑ It does not represent an imminent safety threat by reason of unsecured, damaged, or weak maintenance hole cover(s) or other unsafe condition.</li> </ul>	□ The SSTS has a seepage pit, cesspool, drywell, leaching pit, or other pit — "Failure to Protect Groundwater." □ It has a sewage tank that was designed to be watertight, but subsequently leaks below the designed operating depth — "Failure to Protect Groundwater." □ It presents a threat to public safety by reason of unsecured, damaged, or weak maintenance hole cover(s) or other unsafe condition. "It makes
Company information	Total House of Salety."
company name: Pinky S Sewer Service	Print name: Mick St. Claire
usiness license number: 16.73	Certification number: 69755
personally conducted the work described above as a Designated of Business. I personally conducted the necessary procedures to assert Designated Certified	National Control of the Control of t
Designated Certified andividual's signature:	Date (mm/dd/yyyy): 9/9/22