DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT n 2407128615

Date of Maintenance 9/19/22 Rea	son for Maintenance:	· Compliano	•	
Property Address: 1740 182	and ST N Pro	operty Owner's Name:	sharon fun k	emi
Municipality: Scarde a	State Zip Co	odeGEO	Code/Property I.D. #:	5
What was done (of the sy) tem /	多。 と対象がfile av	langening king kera	aniajjisajienajewojiama	
Tank(s) Pumped	Liquid Level of T	afik in. Sludg	e Level in. Scum Level	in.
Do tanks need to be pumped?			- Scottiffedel	
Yes No (If no provide measurer	nents) Total (Sludge + 5	Scum) / Liquid L	evel = % Sludge & Scu	m
1. Access used to remove septage: Mair		r (Go to #3 helow)	* Tank must be pumped if	this value
2. If maintenance hole was used, were all con			is greater than 25%.	
	reis securely replaced:	Tes I No please ex	orain	
Explanation:				
If owner refuses to allow a Subsurface S them complete and sign the following st	ewage Treatment Syste latement:	m (SSTS) to be pumped	through the maintenance hold	, have
i, · · .	(owner's name), refuse to	allow the removal of sol	ids and liquids through the main	tenance
hole. I understand that removal of solids a				
4. Is the tank designed as a leaky tank? examp	le: seepage pit, cesspool, (drywell, leaching pit		
Tank#1 ☐ Yes ☑ No Verificatio Metho	od Used:			
Tank#2 Yes No Verificatio Metho	<i>*</i>			
5. Is there evidence of tank leakage from a	septic, holding, pretrea	tment or pump tank be	low the operating depth or evi	dence of
damaged, cracked, or structurally unsour	Leaking Out	vers? Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	Yes No	Yes Tino	
Septic/Holding Tank #2	□Yes □No	☐ Yes ☐ No	Yes INO	
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	Yes No	Yes No	Yes No	
6. How many gailons of septage were remov	red?			
Tank#1 Tank#2	Pretreatment Ta	nk Pu	mp Tank 350	
Tank#1 Tank#2				
7. Other information: List any troubleshooti	ng, minor repairs cond	ucted, tank safety conce	rns, or other concerns.	
Talle To C	ng, minor repairs condu	ucted, tank safety conce	rns, or other concerns.	
7. Other information: List any troubleshooti	ng, minor repairs condu Minnesota certified SSTS I or directly supervised oth	Vaintainer that I personal ers in the performance of	rns, or other concerns.	
7. Other information: List any troubleshooti 3. Certification: I hereby certify as a State of Maintainer's Name: Olson's Sewer Service, I	ng, minor repairs condu Minnesota certified SSTS I or directly supervised oth	Vaintainer that I personal ers in the performance of r's Address: 17638 Lyons	rns, or other concerns. ly conducted the work this job.	
7. Other information: List any troubleshooti 3. Certification: I hereby certify as a State of Maintainer's Name: Olson's Sewer Service, I	ng, minor repairs condi Ainnesota certified SSTS I or directly supervised oth nc. Maintaine	Maintainer that I personal ers in the performance of r's Address: 17638 Lyons	rns, or other concerns. ly conducted the work this job.	