DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT Y 5257 9 28613

Date of Maintenance 9/19/22 Rea	son for Maintenance:			
Property Address: 23525 Elmor	est Ave Pro	operty Owner's Name:		•
Municipality: Forest Lake	State MN Zip Co	ode <u>55025</u> GEO	Code/Property I.D. #:	
What was done to the system.	Se translation	ensultement (min) (esc	completed kanksnoup	mbo (I) Sens
Tank(s) Pumped	Liquid Level of T	afik in. Slude	in. Scum Le	vet in.
Sludge and scum measured. Do tanks need to be pumped?	1			
Yes No (If no provide measuren	nents) Total (Sludge + S	icum) / Liquid	Level = % Sludge &	Scum
1. Access used to remove septage: Mair	ntenance Hole Other	(Go to #3 below)	* Tank must be pumper is greater than 25%.	ed if this value
2. If maintenance hole was used, were all cov	ers securely replaced?	Yes No please ex		
Explanation:				
3. If owner refuses to allow a Subsurface S them complete and sign the following st	ewage Treatment Systement:	m (SSTS) to be pumped	f through the maintenance	hole, have
l, ·	(owner's name), refuse to	allow the removal of so	lids and liquids through the i	maintenance
hole. I understand that removal of solids a	S		idered maintenance.	
4. Is the tank designed as a leaky tank? <i>examp</i>	ole: seepage pit, cesspool, c	lrywell, leaching pit		
Tank#1 ☐ Yes - No Verificatio Metho	od Used: Visua	2		33
Tank#2 ☐ Yes ☑ No Verificatio Metho	7,300		····	
5. Is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretrea nd maintenance hole co	tment or pump tank be vers?	low the operating depth o	r evidence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes HNo	☐ Yes ☐ No	Yes Allo	-
Septic/Holding Tank #2	Yes No	Yes No	Yes Atro	· .
Pretreatment Tank	Yes No	Yes No	Yes No	6
Pump Tank	☐ Yes ► No	☐ Yes ♠No	Yes INO	e.
. How many gallons of septage were remo	ved?			
Tank#1 1500 Tank#2 1000	Pretreatment Ta	nk P	ump Tank	
Other information: List any troubleshooti	ng, minor repairs cond	ucted, tank safety conc	erns, or other concerns.	
.Certification: I hereby certify as a State of A and made the observations,	Minnesota certified SSTS lor directly supervised other	Maintainer that I persona ers in the performance o	ily conducted the work f this job.	
Maintainer's Name: Olson's Sewer Service, I	nc. Maintaine	r's Address: 17638 Lyon:	Street NE, Forest Lake, MN	
Maintainer's License #: 216 Mainta	iner's Phone #: 651-464	1-2082	ī	
Maintainer's Signature	A	Date: 9	19/22	