

LOG OF SOIL BORINGS

Along North of
Parking Lot

11823. Point Douglas Drive So. Cottage Grove

Job
Date

05-01-04

Depth Foot	11A	11A	11A	11A
	Black sandy silty loam	Black sandy silt loam	Black sandy silt loam	Black sandy silt loam
Fill?	10gr 2/1	10gr 2/1	10gr 2/1	10gr 2/1
Do not use	medium brown sandy loam	medium to red brown	medium brown	medium brown
	10gr 4/3. 38	medium sand with some	sandy silty loam	sandy silty loam
this area	Red brown to medium to fine sand	pale brown streaks	Red brown fine sand	Red brown fine sand
	5gr 4/3.	5gr 5/3	5gr 4/3	5gr 4/3
	72	76	74	74