DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintena	nce 1/27/22 Re	ason for Maintenance:	n 4512628	814	
Property Address:	9820.20	-11.FC #2	operty Owner's Name:	SUSON DAHI.	eimer
Municipality:		State WVZip C	ode 55025 GEO	Code/Property I.D. #:	4
. What wa	s done to the system is	and the second	leasurements (muscose,	क्वणीवदःग्रह्मात्रावेष्ट्रात	umbed 204
Tank(s) Pumpe	d		А.		
Sludge and scu		Liquid Level of	Tarifk in. Sludg	e Level in. Scum L	evel in.
Do tanks need to be pumped? Yes No (If no provide measurements) Total (Sludge + Scum) / Liquid Level = % Slu				.evel = % Sludge	& Scum
1. Access used to re	emove septage: Ma	intenance Hole Othe	r (Go to #3 below)	* Tank must be pump	ed if this value
2. If maintenance h	ole was used, were all co	vers securely replaced?	Yes No please ex	is greater than 25%.	,
Explanation:					
3. If owner refuses them complete a	to allow a Subsurface ! and sign the following :	Sewage Treatment Systotatement:	em (SSTS) to be pumped	through the maintenance	e hole, have
I,(owner's name), refuse to allow the removal of solids and liquids through the maintenance					
hole. I understand	d that removal of solids a	and liquids through other	access points is not consi	ilds and liquids through the idered maintenance	maintenance
4. Is the tank design	ed as a leaky tank? exam	ple: seepage pit, cesspool,	drywell, leaching pit	ocico mantenance,	
Tank#1 🔲 Yes	-				
_		-			
Tank#2 Yes					
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
. = .	Tank	Leaking Out	Leaking In	Cover Damage	
Se	ptic/Holding Tank #1	Yes ANo	Yes No		-:
	ptic/Holding Tank #2	☐ Yes ☑No	Yes No	Yes No	- .
Pre	etreatment Tank	Yes No	Yes No	Yes No	-
Pu	mp Tank	Yes No	☐ Yes ☐ No	Yes No	-
6. How many gallons of septage were removed?					
Tank #1 Tank #2 Pretreatment Tank Pump Tank					
7. Other information	: List any troubleshoot	ing, minor repairs cond	ucted, tank safety conce	rns, or other concerns.	
8. Certification: The	reby certify as a State of i	Minnesota cortified SSTS	Maintainer that I personal		
and	made the observations,	or directly supervised oth	viaintainer that i personal ers in the performance of	ly conducted the work this job.	
Maintainer's Name:	Olson's Sewer Service,	Inc. Maintaine	r's Address: 17638 Lyons	Street NE, Forest Lake, MN	
Maintainer's License #: 216 Maintainer's Phone #: 651-464-2082					
Maintainer's Signate	ure Donom	Mon	Date: 9	-27-22	