ZIERKE SOIL TESTING

Dave Schwinghammer 21535 Pomroy Ave N Scandia, MN 55073

9/22/2022

Dear Dave Schwinghammer,

At your request, I have conducted a septic inspection to determine the compliance status of your septic system pursuant to Minnesota Rules Chapter 7080.1500.

The compliance test set out in 7080.1500 has three main inquiries: 1). Is the system functioning hydraulically (disposing of effluent in a manner that prevents it from coming in contact with people)? 2). Are the septic tanks water tight? 3). Does the system have sufficient vertical separation between the bottom of the septic system and restrictive layers (bedrock, standing water, seasonally wet layers, etc) to provide full treatment of effluent?

Based off of these criteria, your septic system is <u>compliant</u>. A certification of compliance is in effect for three years from the date it is issued. To be clear, this should not be construed as a guarantee of future system function – there are too many factors that influence the lifespan of a septic system for an inspector to predict or even guess how long a septic system will last. A copy of this report will be filed with your local unit of government for their records.

Sincerely,

Benjamin Zierke

MPCA Lic 119, Cert 9594

Benjamin Zieske

ADDRESS: 28587 Jeffrey Ave Chisago City, MN 55013

PHONE 651-249-1346

EMAIL benzierke@gmail.com



Compliance inspection report form

Existing Subsurface Sewage Treatment System (SSTS)

520 Lafayette Road North St. Paul, MN 55155-4194

Doc Type: Compliance and Enforcement

Instructions: Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance. Instructions for filling out this form are located on the Minnesota Pollution Control Agency (MPCA) website at https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf.

Property information	Local tracking number:
Parcel ID# or Sec/Twp/Range: 1303220130003	Reason for Inspection Sale
Local regulatory authority info: Washington County	
Property address: 21535 Pomroy Ave N Scandia, MN 55073	
Owner/representative: Dave Schwinghammer	Owner's phone: 651-303-6024
Brief system description: Pre-cast holding tank	· · · ·
System status	
System status on date (mm/dd/yyyy): 9/22/2022	
□ Compliant – Certificate of compliance*	☐ Noncompliant - Notice of noncompliance
(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and	Systems failing to protect ground water must be upgraded, replaced, or use discontinued within the time required by local ordinance.
abatement under section 145A.04, subdivision 8 is discovered or a shorter time frame exists in Local Ordinance.)	An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt
*Note: Compliance indicates conformance with Minn. R. 7080.1500 as of system status date above and does not guarantee future performance.	of this notice or within a shorter period if required by local ordinance or under section 145A.04 subdivision 8.
Reason(s) for noncompliance (check all applicate	ole)
☐ Impact on public health (Compliance component #1) – Imminent threat to public health and safety
☐ Tank integrity (Compliance component #2) – Failing	to protect groundwater
☐ Other Compliance Conditions (Compliance components)	ent #3) – Imminent threat to public health and safety
☐ Other Compliance Conditions (Compliance components)	ent #3) – Failing to protect groundwater
System not abandoned according to Minn. R. 7080.	2500 (Compliance component #3) – Failing to protect groundwater
☐ Soil separation (Compliance component #5) – Failin	g to protect groundwater
☐ Operating permit/monitoring plan requirements (Cor	mpliance component #4) – Noncompliant - local ordinance applies
Comments or recommendations	
No issues with tank or alarm observed during site visit 9/2	21/2022.
Certification	
	to determine the compliance status of this system. No determination of wn conditions during system construction, possible abuse of the system,
,	and correct, to the best of my knowledge, and that this information can be
Business name: Zierke Soil Testing	Certification number: 9594
Inspector signature: Benzin Zierke	License number: 119
(This document has been electronically sig	ned) Phone: 651-249-1346
Necessary or locally required supporting do	cumentation (must be attached)
☐ Soil observation logs ☐ System/As-Built ☐ Locally re	equired forms
Other information (list):	

System discharges sewage to the ground surface System discharges sewage to drain tile or surface waters. System causes sewage backup into dwelling or establishment. Any "yes" answer above indicates the system is an imminent threat to public health and safety. Describe verification methods and results: None of the above observed during site visit 9/21/2022. Ank integrity — Compliance component #2 of 5 Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Ves* No	Compliance criteria:		Attached supporting documentation:	
System discharges sewage to drain lile or surface waters. System causes sewage backup into dwelling or establishment. Any "yes" answer above indicates the system is an imminent threat to public health and safety. Describe verification methods and results: None of the above observed during site visit 9/21/2022. No		☐ Yes* ⊠ No		
Any "yes" answer above indicates the system is an imminent threat to public health and safety. Describe verification methods and results: None of the above observed during site visit 9/21/2022. nk integrity — Compliance component #2 of 5 Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance		☐ Yes* ⊠ No	<u> </u>	
In the prity — Compliance component #2 of 5 Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: Date of maintenance Existing tank integrity assessment (Attach) Date of maintenance		☐ Yes* ⊠ No		
None of the above observed during site visit 9/21/2022. None of the above observed supporting documentation: None of maintenance business: Smilles			-	
nk integrity – Compliance component #2 of 5 Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? Attached supporting documentation: □ Yes* □ No □ Yes* □ No Name of maintenance business: Smilies License number of maintenance business: 2428 □ Date of maintenance: 9/21/2022 □ Existing tank integrity assessment (Attach) □ Date of maintenance	Describe verification methods and	results:		
nk integrity – Compliance component #2 of 5 Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/2022 Existing tank integrity assessment (Attach) Date of maintenance	lone of the above observed during s	ite visit 9/21/2022.		
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? Attached supporting documentation: ☐ Yes* ☐ No ☐ Yes* ☐ No ☐ Yes* ☐ No ☐ License number of maintenance business: 2428 ☐ Date of maintenance: 9/21/2022 ☐ Existing tank integrity assessment (Attach) ☐ Date of maintenance				
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? Attached supporting documentation: ☐ Yes* ☑ No ☐ Yes* ☑ No ☐ Yes* ☑ No ☐ License number of maintenance business: 2428 ☐ Date of maintenance: 9/21/2022 ☐ Existing tank integrity assessment (Attach) ☐ Date of maintenance				
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? Attached supporting documentation: □ Yes* □ No □ License number of maintenance business: 2428 □ Date of maintenance: 9/21/2022 □ Existing tank integrity assessment (Attach) □ Date of maintenance				
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? Attached supporting documentation: □ Yes* □ No □ License number of maintenance business: 2428 □ Date of maintenance: 9/21/2022 □ Existing tank integrity assessment (Attach) □ Date of maintenance				
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/2022 Existing tank integrity assessment (Attach) Date of maintenance				
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/2022 Existing tank integrity assessment (Attach) Date of maintenance				
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/2022 Existing tank integrity assessment (Attach) Date of maintenance				
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? Attached supporting documentation: □ Yes* □ No □ License number of maintenance business: 2428 □ Date of maintenance: 9/21/2022 □ Existing tank integrity assessment (Attach) □ Date of maintenance				
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? Attached supporting documentation: □ Yes* □ No □ License number of maintenance business: 2428 □ Date of maintenance: 9/21/2022 □ Existing tank integrity assessment (Attach) □ Date of maintenance				
System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/2022 Existing tank integrity assessment (Attach) Date of maintenance				
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? Attached supporting documentation: □ Yes* □ No □ License number of maintenance business: 2428 □ Date of maintenance: 9/21/2022 □ Existing tank integrity assessment (Attach) □ Date of maintenance				
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/2022 Existing tank integrity assessment (Attach) Date of maintenance				
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? Attached supporting documentation: □ Yes* □ No □ License number of maintenance business: 2428 □ Date of maintenance: 9/21/2022 □ Existing tank integrity assessment (Attach) □ Date of maintenance				
System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/2022 Existing tank integrity assessment (Attach) Date of maintenance	ala indonvida a Compalia a co		-£ F	
System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/2022 Existing tank integrity assessment (Attach) Date of maintenance	n k integrity – Compliance	component #2	of 5	
cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/2022 Existing tank integrity assessment (Attach) Date of maintenance		component #2		
or other pit? Sewage tank(s) leak below their designed operating depth? Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/2022 □ Existing tank integrity assessment (Attach) Date of maintenance		component #2		
Sewage tank(s) leak below their designed operating depth? License number of maintenance business: 2428 Date of maintenance: 9/21/2022 Existing tank integrity assessment (Attach) Date of maintenance	Compliance criteria:	· 	Attached supporting documentation:	
designed operating depth? Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit,	· 	Attached supporting documentation: ☑ Empty tank(s) viewed by inspector	
Date of maintenance: 9/21/2022 Existing tank integrity assessment (Attach) Date of maintenance	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit,	· 	Attached supporting documentation: ☑ Empty tank(s) viewed by inspector	
Date of maintenance	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes* ☑ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies	<u>.</u>
4 414 3	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes* ☑ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: 2428	
If yes, which sewage tank(s) leaks: (mm/dd/yyyy): (must be within three years)	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes* ☑ No	Attached supporting documentation: ☑ Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/20	
	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes* ☑ No	Attached supporting documentation: ☑ Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/20 ☐ Existing tank integrity assessment (Attach) Date of maintenance)22
Any "yes" answer above indicates the system (See form instructions to ensure assessment complies Minn, R. 7082.0700 subp. 4 B (1))	Compliance criteria: System consists of a seepage pit, besspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth?	☐ Yes* ☑ No	Attached supporting documentation: ☑ Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/20 ☐ Existing tank integrity assessment (Attach) Date of maintenance)22
	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/20 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three year) (See form instructions to ensure assessment comp	022 ars)
	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks:	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/20 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three year of the companies) (See form instructions to ensure assessment companies) Minn. R. 7082.0700 subp. 4 B (1))	022 ars) plies wit
☐ Tank is Noncompliant (pumping not necessary – explain be	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/20 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three year of the composition of the	022 ars) plies with
	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/20 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three year of the composition of the	022 ars) plies with
☐ Tank is Noncompliant (pumping not necessary – explain be	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indictions failing to protect groundwate	☐ Yes* ☑ No ☐ Yes* ☑ No ☐ Yes* ☑ No ☐ ates the system er.	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/20 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three year of the composition of the	022 ars) plies with
, , ,	Compliance criteria: System consists of a seepage pit, besspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth?	☐ Yes* ☑ No	Attached supporting documentation: ☑ Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/20 ☐ Existing tank integrity assessment (Attach) Date of maintenance)22
	Compliance criteria: System consists of a seepage pit, besspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth?	☐ Yes* ☑ No	Attached supporting documentation: ☑ Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/20 ☐ Existing tank integrity assessment (Attach) Date of maintenance)22
	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks:	☐ Yes* ☑ No ☐ Yes* ☑ No	Attached supporting documentation: ☑ Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/20 ☐ Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three year)22 ars)
	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks:	☐ Yes* ☑ No ☐ Yes* ☑ No	Attached supporting documentation: ☑ Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/20 ☐ Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three year)22 ars)
is failing to protect groundwater Minn. R. 7082.0700 subp. 4 B (1))	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/20 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three year) (See form instructions to ensure assessment comp)22 ars)
	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/20 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three year) (See form instructions to ensure assessment comp)22 ars)
	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/20 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three year of the companies) (See form instructions to ensure assessment companies) Minn. R. 7082.0700 subp. 4 B (1))	o22 ars) plies wi
	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/20 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three year of the companies) (See form instructions to ensure assessment companies) Minn. R. 7082.0700 subp. 4 B (1))	o22 ars) plies wi
☐ Tank is Noncompliant (pumping not necessary – explain be	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/20 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three year of the composition of the	o22 ars) plies wi
☐ Tank is Noncompliant (pumping not necessary – explain be	Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 9/21/20 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three year of the composition of the	o22 ars) plies wi

Р	roperty Address: 21535 Pomroy Ave N Scandia, MN 55073	
	usiness Name: Zierke Soil Testing	Date: 9/22/2022
3.	Other compliance conditions – Compliance component #3 of 5	
	3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unse	ecured?
	☐ Yes* ☒ No ☐ Unknown	
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safet	:y? ☐ Yes* ☒ No ☐ Unknown
	*Yes to 3a or 3b - System is an imminent threat to public health and safety.	
	3c. System is non-protective of ground water for other conditions as determined by inspector?	☐ Yes* ⊠ No
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	☐ Yes* ⊠ No
	*Yes to 3c or 3d - System is failing to protect groundwater.	
	Describe verification methods and results:	
	Attached supporting documentation: ☐ Not applicable ☑	
4.	Operating permit and nitrogen BMP* – Compliance component #4 o	of 5 🛭 Not applicable
	Is the system operated under an Operating Permit? ☐ Yes ☐ No	If "yes", A below is required
	Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No	
	BMP = Best Management Practice(s) specified in the system design	•
	If the answer to both questions is "no", this section does not need to be completed	d.
	Compliance criteria:	
	a. Have the operating permit requirements been met?	
	b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No	
	Any "no" answer indicates noncompliance.	
	Describe verification methods and results:	
	Describe verification methods and results.	
	Attached supporting documentation: Operating permit (Attach)	
	Attached supporting documentation:	

https://www.pca.state.mn.us wq-wwists4-31b • 4/28/2021

usiness Name: Zierke Soil Testing		Date: 9/22/2022
Soil separation – Compliance co	mponent #5 o	f 5
Date of installation 2016 (mm/dd/yyyy)	_	
Shoreland/Wellhead protection/Food beverage lodging? Compliance criteria (select one):	☐ Yes No	Attached supporting documentation: Soil observation logs completed for the report Two previous verifications of required vertical separations
5a. For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:	☐ Yes ☐ No*	Not applicable (No soil treatment area) □
Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.		
5b. Non-performance systems built April 1, 1996, or later or for non- performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment: Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*	☐ Yes ☐ No*	Indicate depths or elevations A. Bottom of distribution media B. Periodically saturated soil/bedrock C. System separation D. Required compliance separation* *May be reduced up to 15 percent if allowed by Local Ordinance.
5c. "Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules 7080. 2350 or 7080.2400 (Intermediate Inspector License required ≤ 2,500 gallons per day; Advanced Inspector License required > 2,500 gallons per day)	☐ Yes ☐ No*	
Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock.		

Describe verification methods and results:

Upgrade requirements: (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

800-657-3864

https://www.pca.state.mn.us wq-wwists4-31b • 4/28/2021

