ZIERKE SOIL TESTING

Tamara Early 15101 220th St N Scandia, MN 55073

September 27th, 2022

Dear Tamara Early,

At your request, I have conducted a septic inspection to determine the compliance status of your septic system pursuant to Minnesota Rules Chapter 7080.1500.

The compliance test set out in 7080.1500 has three main inquiries: 1). Is the system functioning hydraulically (disposing of effluent in a manner that prevents it from coming in contact with people)? 2). Are the septic tanks water tight? 3). Does the system have sufficient vertical separation between the bottom of the septic system and restrictive layers (bedrock, standing water, seasonally wet layers, etc) to provide full treatment of effluent?

Based off of these criteria, your system is <u>non-compliant</u> due to (2) two block-style bottomless septic tanks that are not watertight. Therefore, this system is considered "failing to protect groundwater" and <u>is not considered an imminent threat to public health</u>. I am required to provide copies of this report to you and to Washington County. You should contact them as to the next steps that will be required to bring the system into compliance.

Sincerely,

Benjamin Zierke

MPCA Lic 119, Cert 9594

Benjamin Zierke

ADDRESS: 28587 Jeffrey Ave Chisago City, MN 55013

PHONE 651-249-1346 EMAIL benzierke@gmail.com



Compliance inspection report form

Existing Subsurface Sewage Treatment System (SSTS)

520 Lafayette Road North St. Paul, MN 55155-4194

Doc Type: Compliance and Enforcement

Instructions: Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance. Instructions for filling out this form are located on the Minnesota Pollution Control Agency (MPCA) website at https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf.

Property information	Local tracking number:	
Parcel ID# or Sec/Twp/Range: 1403220110001	Reason for Inspection Sale	
Local regulatory authority info: Washington County		
Property address: 15101 220th St N Scandia, MN 55073		
Owner/representative: Tamara Early	Owner's phone: 651-366-0599	
Brief system description: (2) bottomless block style tanks		
System status		
System status on date (mm/dd/yyyy): _ 9/27/2022		
☐ Compliant – Certificate of compliance*	Noncompliant − Notice of noncompliance	
(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and	Systems failing to protect ground water must be upgraded, replaced, or use discontinued within the time required by local ordinance.	
abatement under section 145A.04, subdivision 8 is discovered or a shorter time frame exists in Local Ordinance.)	An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt	
*Note: Compliance indicates conformance with Minn. R. 7080.1500 as of system status date above and does not guarantee future performance.	of this notice or within a shorter period if required by local ordinance or under section 145A.04 subdivision 8.	
Reason(s) for noncompliance (check all applicate	ole)	
☐ Impact on public health (Compliance component #1)) – Imminent threat to public health and safety	
☐ Tank integrity (Compliance component #2) – Failing	to protect groundwater	
☐ Other Compliance Conditions (Compliance components)	ent #3) – Imminent threat to public health and safety	
☐ Other Compliance Conditions (Compliance components)	ent #3) – Failing to protect groundwater	
☐ System not abandoned according to Minn. R. 7080.	2500 (Compliance component #3) – Failing to protect groundwater	
☐ Soil separation (Compliance component #5) – Failin	g to protect groundwater	
☐ Operating permit/monitoring plan requirements (Cor	mpliance component #4) – Noncompliant - local ordinance applies	
Comments or recommendations		
System consists of two block-style tanks without bottoms two 800 gallon bottomless block tanks.	. Confirmed with previous maintainer (Smilies) that their records show	
Certification		
	to determine the compliance status of this system. No determination of wn conditions during system construction, possible abuse of the system,	
By typing my name below, I certify the above statements to be true used for the purpose of processing this form.	and correct, to the best of my knowledge, and that this information can be	
Business name: Zierke Soil Testing	Certification number: 9594	
Inspector signature: Benjamin Zierke	License number: 119	
(This document has been electronically sig	ned) Phone: 651-249-1346	
Necessary or locally required supporting do	cumentation (must be attached)	
☐ Soil observation logs ☐ System/As-Built ☐ Locally re	equired forms	
☐ Other information (list):		

pact on public health – Co	omnliance comr	nonent #1 of 5
Compliance criteria:	omphance comp	Attached supporting documentation:
System discharges sewage to the ground surface	☐ Yes* ⊠ No	☐ Other: ☐ Not applicable
System discharges sewage to drain tile or surface waters.	☐ Yes* ☒ No	
System causes sewage backup into dwelling or establishment.	☐ Yes* ⊠ No	
Any "yes" answer above indicates imminent threat to public health an		
Describe verification methods and	results:	
None of the above observed during s	ite visit 9/23/2022.	
nk integrity – Compliance	component #2	of 5
nk integrity – Compliance Compliance criteria:	component #2	of 5 Attached supporting documentation:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit,	component #2	Attached supporting documentation: ☐ Empty tank(s) viewed by inspector
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	Yes* ⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit,	·	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	Yes* ⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	Yes* ⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	Yes* ⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach)
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth?	Yes* ⊠ No Yes* ⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years)
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	Yes* ⊠ No Yes* ⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (See form instructions to ensure assessment complies to
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	Yes* ⊠ No Yes* ⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years) (See form instructions to ensure assessment complies of Minn. R. 7082.0700 subp. 4 B (1))
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	Yes* ⊠ No Yes* ⊠ No Yes* ⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (See form instructions to ensure assessment complies Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necessary – explain be

Р	roperty Address: 15101 220 th St N Scandia, MN 55073	
	usiness Name: Zierke Soil Testing	Date: 9/27/2022
3.	Other compliance conditions – Compliance component #3 of 5	
	3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unse	cured?
	☐ Yes* ☑ No ☐ Unknown	
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety	/? ☐ Yes* ☒ No ☐ Unknown
	*Yes to 3a or 3b - System is an imminent threat to public health and safety.	
	3c. System is non-protective of ground water for other conditions as determined by inspector?	☐ Yes* ⊠ No
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	☐ Yes* ⊠ No
	*Yes to 3c or 3d - System is failing to protect groundwater.	
	Describe verification methods and results:	
	Attached supporting documentation: ☐ Not applicable ☑	
	Attached supporting documentation. Not applicable	
4.	Operating permit and nitrogen BMP* – Compliance component #4 o	f 5 🕅 Not applicable
		f "yes", A below is required
	Is the system required to employ a Nitrogen BMP specified in the system design? Yes No I	f "yes", B below is required
	BMP = Best Management Practice(s) specified in the system design	
	If the answer to both questions is "no", this section does not need to be completed	l.
	Compliance criteria:	
	a. Have the operating permit requirements been met? ☐ Yes ☐ No	
	b. Is the required nitrogen BMP in place and properly functioning? $\ \square$ Yes $\ \square$ No	
	Any "no" answer indicates noncompliance.	
	Describe verification methods and results:	
	Attached supporting documentation: Operating permit (Attach)	

https://www.pca.state.mn.us wq-wwists4-31b • 4/28/2021

ısiness Name: Zierke Soil Testing		Date: 9/27/2022	
Soil separation – Compliance cor	nponent #5 c	f 5	
Date of installation 1972 (mm/dd/yyyy)	_		
Shoreland/Wellhead protection/Food beverage lodging? Compliance criteria (select one):	☐ Yes ⊠ No	Attached supporting documentation: ☐ Soil observation logs completed for the report ☐ Two previous verifications of required vertical separations.	
5a. For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:	☐ Yes ☐ No*		
Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.			
5b. Non-performance systems built April 1, 1996, or later or for non- performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:	☐ Yes ☐ No*	A. Bottom of distribution media B. Periodically saturated soil/bedrock	
Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*		C. System separation D. Required compliance separation* *May be reduced up to 15 percent if allowed by Local Ordinance.	
5c. "Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules 7080. 2350 or 7080.2400 (Intermediate Inspector License required ≤ 2,500 gallons per day; Advanced Inspector License required > 2,500 gallons per day)	☐ Yes ☐ No*		
Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock.			

Describe verification methods and results:

Upgrade requirements: (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

800-657-3864

https://www.pca.state.mn.us wq-wwists4-31b • 4/28/2021

