

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

| This section must be completed in its ent | rety to constitute a va | id maintenance p | ermit. This permit | must be completed | |
|---|-------------------------------|--|----------------------|---------------------|--|
| prior to performing maintenance a | ctivities and remain on | site for the durat | ion of the maintena | nce activity. | |
| Date of Maintenance: $5.27.22$ Re | ason for Maintenance: | Routine | | | |
| Property Address: 5196 After | | | ame: Gree | ales | |
| | | | | | |
| Municipality: Atton ZIP: | Property Ide | ntification Number: | | | |
| Maintenance Permit No: <u>m 7452 は74</u> | ∲ % Maintainer Name ar | d License No. Pink | y's Environmental Se | ewer Service/ L1673 | |
| | | | | | |
| Maintenance Performed | Tank Meas | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped | Liquid Level of | Liquid Level of Tank ——— in | | | |
| ☐ Sludge and scum measured Sludge Level in Tank in Scum Level in Tank | | | | | |
| Do tanks need to be pumped? | Sludge + Scum | Sludge + Scum / Liquid Level X 100 | | | |
| Yes No (if no provide measurem | ents) = % Sludge & Sc | = % Sludge & Scum Tanks must be pumped if 25% or greater | | | |
| 1. Access used to remove septage: \Box Mai | ntenance Hole Other (e | nter authorization co | ode) | | |
| 2. Were all covers securely replaced? | Yes No | | | | |
| 3. Is there evidence of tank leakage from | | eatment or pump | tank below the ope | rating depth or | |
| evidence of damaged, cracked, or stru | icturally unsound main | tenance hole cove | rs? Yes No | | |
| Tank | Leaking Out | Leaking In | Cover Damage | | |
| Septic/Holding Tank #3 | ☐ Yes ☐ No | ☐ Yes ☑No | ☐ Yes ☑ No | • | |
| Septic/Holding Tank #2 | Yes No | ☐ Yes ☐ No | ☐ Yes ☑ No | | |
| Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| 4. How many gallons of septage were rem | oved? | 20 | | | |
| Tank #1 1000 gal Tank #2 100 | gal Pretreatment | tankg | al Pump Tank | gal | |
| 5. Other information: List any troubleshoo | oting, minor repairs co | nducted, tank safe | ty concerns, or oth | er concerns. | |
| | | | | - | |
| | | | | | |
| 6. Location of septage disposal: | -1991 | | | | |
| | | | | | |
| ı | Pinky's Environmental Se | ewer Service Inc. | | | |

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673