ess Name: SS Septic Solutions, LLC.		Date: 9/29/2022
pact on public health — Compliance criteria:	ompliance o	
System discharges sewage to the	☐ Yes* ⊠ No	Attached supporting documentation: Other:
ground surface System discharges sewage to drain	☐ Yes* ⊠ No	☐ Not applicable
tile or surface waters. System causes sewage backup into	☐ Yes* ⊠ No	
dwelling or establishment. Any "yes" answer above indicates	the system is	
imminent threat to public health ar	nd safety.	
Describe verification methods and	l results:	
nk integrity – Compliance	componen	- #2 of 5
nk integrity — Compliance	componen	
nk integrity – Compliance Compliance criteria:	componen	: #2 of 5 Attached supporting documentation:
Compliance criteria: System consists of a seepage pit,	componen □ Yes* ⋈ No	
Compliance criteria:	T	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	T	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes* ⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: 9/29/2022
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes* ⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes* ⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: 9/29/2022 Existing tank integrity assessment (Attach) Date of maintenance
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes* ⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: 9/29/2022 Existing tank integrity assessment (Attach)
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth?	☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years)
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks:	☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years)
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years) (See form instructions to ensure assessment complies within R. 7082.0700 subp. 4 B (1))
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Meyers License number of maintenance business: Date of maintenance: 9/29/2022 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years) (See form instructions to ensure assessment complies within R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necessary – explain below the substance of the support of
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates is failing to protect groundwate.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No ates the system	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years) (See form instructions to ensure assessment complies within R. 7082.0700 subp. 4 B (1))
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No ates the system	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Meyers License number of maintenance business: Date of maintenance: 9/29/2022 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years) (See form instructions to ensure assessment complies of Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necessary – explain below
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates is failing to protect groundwate.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No ates the system	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Meyers License number of maintenance business: Date of maintenance: 9/29/2022 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years) (See form instructions to ensure assessment complies of Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necessary – explain below
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates is failing to protect groundwate.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No ates the system	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Meyers License number of maintenance business: Date of maintenance: 9/29/2022 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years) (See form instructions to ensure assessment complies within R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necessary – explain below the substance of the support of
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates is failing to protect groundwate.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No ates the system	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Meyers License number of maintenance business: Date of maintenance: 9/29/2022 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years) (See form instructions to ensure assessment complies within R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necessary – explain below
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates is failing to protect groundwate.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No ates the system	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Meyers License number of maintenance business: Date of maintenance: 9/29/2022 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years) (See form instructions to ensure assessment complies of Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necessary – explain below
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicates is failing to protect groundwate.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No ates the system	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Meyers License number of maintenance business: Date of maintenance: 9/29/2022 Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years) (See form instructions to ensure assessment complies within R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necessary – explain below the substance of the support of