

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety prior to performing maintenance activit					
Date of Maintenance: 5-20-20 Reason			outing.		
Property Address: 7484 Granda Cir	111	Property Owner's N	ame: Anarda	& Norther SP	
Municipality: Cottage Grove ZIP:	Property Ide	ntification Number:			
Maintenance Permit No: 0790402575	Maintainer Name a	nd License No. <u>Pink</u>	y's Environmental Se	wer Service/ L167	
Maintenance Performed	Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of	Liquid Level of Tank — in			
☐ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)	= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of tank leakage from a sepevidence of damaged, cracked, or structur  Tank				ating depth or	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed	?				
Tank #1 1000 gal Tank #2 500	_gal Pretreatmen	tankga	al Pump Tank	gal	
5. Other information: List any troubleshooting					
	, /				
6. Location of septage disposal:	W/				

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673