## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT \$ 1573c 25821

Date of Maintenance	ason for Maintenance:			
Property Address: 2008 8	org V. VA bligh	perty Owner's Nan	ne Rom Hum	242 242
Municipality: Scandia	State Zip Co	de	GEO Code/Property I.D. #:	200
aWhat was done to the system of	i i i i i i i i i i i i i i i i i i i	as Ure ments (mu	(eta somplace di carica)	Oppumped sec
☐ Sludge and scum measured.	Liquid Level of Ta	rikin.	Sludge Level in. Sc	cum Level in.
Do tanks need to be pumped?  Yes No (If no provide measure	Total (Sludge + So	cum) / Lio	quid Level = % SI	udge & Scum
1. Access used to remove septage: Mai				pumped if this value
is greater than 25%.  2. If maintenance hole was used, were all covers securely replaced? Yes No please explain				
Explanation:				
3. If owner refuses to allow a Subsurface sthem complete and sign the following s	Sewage Treatment Syster tatement:	n (SSTS) to be pur	nped through the mainte	nance hole, have
l, (owner's name), refuse to allow the removal of solids and liquids through the maintenance				
hole. I understand that removal of solids a	and liquids through other a	ccess points is not	COnsidered maintenance	in the maintenance
<b>4.</b> Is the tank designed as a leaky tank? $exam_i$	ple: seepage pit, cesspool, di	vwell. leachina nit	TO THE STATE OF TH	
Tank#1 Yes No Verificatio Meth		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
Tank#2 Yes No Verificatio Meth	od Used:			
5. Is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretreat	nent or pump tan	k below the operating de	pth or evidence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	Yes No	Yes No	
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	<del></del>
Pump Tank	Yes No	Yes No	Yes No	
. How many gallons of septage were remo	ved?	0 10 2010		
Tank#1 Tank#2	Pretreatment Tank		Pump Tank	
Other information: List any troubleshooti	ing, minor repairs conduc	ted, tank safety c	oncerns, or other concern	s.
Certification: I hereby certify as a State of A and made the observations, of	Ainnesota certified SSTS Ma or directly supervised other	intainer that I pers s in the performan	onally conducted the work ce of this job.	
Maintainer's Name: Olson's Sewer Service, I			ons Street NE, Forest Lake,	MN
Maintainer's License #: 216 Mainta	iner's Phone #: 651-464-2	082		ı
Maintainer's Signature		Date:	1/30/22	