## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT

Date of Maintenance 8 222 Re	ason for Maintenance:	044824	28582	
Property Address: 7040 n.S.k	mB-M- PI	operty Owner's Name:	Dollace and non	
Municipality: From Jake	State Zip C	ode GEC	Code/Property I.D. #:	
SCA SV hat was done to the system's	a tanki	Measurements (musobe	complete elicopizazione	VIVE STATE
Tank(s) Pumped		DATES - LEVEL - VIEW -		4.00
Sludge and scum measured.	Liquid Level of	Tarik in. Sludg	ge Level in. Scum Level	in.
Do tanks need to be pumped?	Total (Chudan .	<b>.</b>		
Yes No (If no provide measure	ments) Total (Sludge +	Scum) / Liquid	.evel = % Sludge & Scu	m
1. Access used to remove septage: Mai		-	* Tank must be pumped if	this value
2. If maintenance hole was used, were all co	vers securely replaced?	Yes No please ex	is greater than 25%.	
Explanation:		•	,	
<ol><li>If owner refuses to allow a Subsurface S them complete and sign the following s</li></ol>	Sewage Treatment Systemater Systems   Statement:	em (SSTS) to be pumped	through the maintenance hole	, have
l, ·				
	(Owner's name), refuse t	o allow the removal of so	lids and liquids through the main	tenance
hole. I understand that removal of solids a 4. Is the tank designed as a leaky tank? example 1.	nia idaias futondu otuei	access points is not cons	idered maintenance.	
			wandsit 10% Signat	<i>''</i>
La va Ellina valuento meni	Joseph Joseph	1 1414		
Tank#2 ☐ Yes ☐ No Verificatio Meth	od Used: Numpea	Tank		35
<ol><li>Is there evidence of tank leakage from a damaged, cracked, or structurally unsou</li></ol>	septic, holding, pretrea	itment or pump tank be	low the operating depth or evid	lence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	Yes No		
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No		Yes No	
Pump Tank	Yes No	Yes No	Yes No	
6. How many gallons of septage were removed		Yes No	Yes No	
Tank#1 408 Tank#2 500		nk p.	mp Tank	
7. Other information: List any troubleshooti	formed	acted, tank safety conce	rns, or other concerns.	
8. Certification: I hereby certify as a State of A	Ainnesota certified SSTS I	Maintainer that I personal	he conducto data	
and made the observations, o	or directly supervised oth	ers in the performance of	this job.	
Maintainer's Name: Olson's Sewer Service, I			Street NE, Forest Lake, MN	
Maintainer's License #: 216 Mainta	iner's Phone #: 651-464		f	
Maintainer's Signature	>		. /	
		Date: 8	ZZ122/	