## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT

Date of Main	Itenance 10-6-12 Re	ason for Maintenance:	n 5645	31135	
Property Ado	dress: 8408 Jewe	1 AUR P	roperty Owner's Name:	Shanna Sen	2
Municipality:	57: 1 water	State Zip C	ode GEC	Code/Property I.D. #:	·
HILLS ALVANDADA	(twas done to the system o	Media inid		anijarahtenjandar	
Tank(s) Pu	-		- A.		
	d scum measured.	Liquid Level of	Tarik in. Slude	ge Level in. Scum Le	evel in
	need to be pumped?	Total (Sludge +	Scum) / Liquid	level = 06 Chidae 6	
	No (If no provide measure	ments)		Level = % Sludge &	/ >cum
1. Access used	to remove septage: Mai	ntenance Hole 🔲 Othe	r (Go to #3 below)	* Tank must be pumpe	ed if this value
2. If maintenan	nce hole was used, were all co	vers securely replaced?	X Yes T No please ex	is greater than 25%.	
Explanation:		•		<b>,</b>	
3. If owner refi	uses to allow a Subsurface S ete and sign the following s	iewage Treatment Systetatement:	em (SSTS) to be pumped	through the maintenance	hole, have
<b>I,</b> :	-		o allow the removal of a	Policie de la companya della companya della companya de la companya de la companya della company	
hole. I under	stand that removal of solids a	nd liquids through other	access points is not con-	lids and liquids through the i	maintenance
4. Is the tank de	signed as a leaky tank? exam	ple: seepage pit. cesspool.	drwell leaching nit	idered maintenance.	
	es 🖄o Verificatio Meth		, con, cooning pic		
Tank#2	es No Verificatio Meth	ہ۔ ۔۔۔۔۔۔۔۔۔ Ad Usad:			-
damaged, cra	ence of tank leakage from a ocked, or structurally unsou	septic, noiding, pretrea nd maintenance hole co	itment or pump tank be overs?	low the operating depth or	evidence of
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes No	Yes No	Yes TiNo	
	Septic/Holding Tank #2	Yes No	Yes No	Yes No	e.
	Pretreatment Tank	Yes No	Yes No	Yes No	
	Pump Tank	Yes No	☐ Yes ☐ No	Yes No	
6. How many ga	lions of septage were remov				
Tank#1 /	777 ) Tank#2 //77				
130		Pretreatment Ta		mp Tank	
7. Other informa	tion: List any troubleshooti	ng, minor repairs condu	acted, tank safety conce	rns, or other concerns.	
8. Certification:	I hereby certify as a State of A	Ainnesota certified SSTS A	Maintainer that I personal	ly conducted the work	-
	and made the observations, o		ers in the performance of	this job.	
Maintainer's Na	me: Olson's Sewer Service, I	nc. Maintaine	r's Address: 17638 Lyons	Street NE, Forest Lake, MN	
Maintainer's Lic	ense #: 216 Mainta	iner's Phone #: 651-464		,	
Maintainer's Sig	nature A	71	Date: 10	1-6-22	
	/	7		<del>-</del>	