DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Main	tenance 10 12 22 Re	ason for Maintenance:	a 5333 a 2	08830	
Property Add	ress: 9038 - 170+2	SH.D. P	roperty Owner's Name:	John Brus	10
Municipality:	Stillister	State Zip (Code GEC	Code/Property I.D. #:	
, Z Z Wha	was done (oane system).	4 7 1100	Mariu emana kulukara	 សភារានទៅសក់សាក្រសាក	
Tank(s) Pur	mped				
Sludge and scum measured.		Liquid Level of	Taffik in. Slude	ge Level in. Scum Leve	e i in
	eed to be pumped?	Total (Sludge +	Scum) / Liquid	evel – % Sluden 8 s	
	No (If no provide measure	ments)			
	to remove septage: Mal			 * Tank must be pumped is greater than 25%. 	if this valu
2. If maintenan	ce hole was used, were all co	vers securely replaced?	Yes No please ex	plain	
Explanation:					
3. If owner refu	ises to allow a Subsurface S	Sewage Treatment Syst	em (SSTS) to be pumped	through the maintenance h	olo have
tnem comple	ete and sign the following s	tatement:	H1	and and manifeliance in	Ole, nave
l,		(owner's name), refuse t	o allow the removal of so	ids and liquids through the m	aintenanco
hole. I unders	stand that removal of solids a	ind liquids through other	access points is not cons	idered maintenance.	anner mine
4. Is the tank de	signed as a leaky tank? exam	ple: seepage pit, cesspool,	drywell, leaching pit		
Tank#1 🔲 Y	es Ko Verificatio Meth	od Used:			
Tank#2 🔲 Y	es No Verificatio Meth	od Used:			
5. is there evide damaged, cra-	nce of tank leakage from a cked, or structurally unsou	septic, holding, pretrea	ntment or pump tank be	low the operating depth or e	vidence of
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes No	Yes No	Yes PiNo	
	Septic/Holding Tank #2	Yes No	Yes No	Yes ZWo	
	Pretreatment Tank	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐No	Yes to	Yes Two	
6. How many gal	ions of septage were remov	ved?			
Tank#1 1500	Tank#2 1000	Pretreatment Ta	nkPu	mp Tank 600	
7. Other informat	tion: List any troubleshooti	ng, minor repairs cond	acted, tank safety conce	rns, or other concerns.	
1					
8. Certification: 1	hereby certify as a State of A and made the observations, o	Ainnesota certified SSTS I or directly supervised oth	Maintainer that I personallers in the performance of	y conducted the work this job.	
	me: Olson's Sewer Service, i			Street NE, Forest Lake, MN	
Maintainer's Lice	ense #: 216 Mainta	iner's Phone #: 651-464	-2082	ſ	
Maintainer's Sig	N) Look	Date:	-12.22	