## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Mainten	ance 10/8/22 Rea	son for Maintenance:	P 0353 W 8	18825	
Property Addres	9877-2197	Pro Car Rect	operty Owner's Name:	panne Ologn	
Municipality:	Hat Forn F	State MN Zip C	ode 55025 GEO	Code/Property I.D. #:	2,
3/2 AWhat w	as done (othersy) tem (	i e i grina	leisü <b>re</b> meniskimukosis	opplete HernenOppmin	ed S
☑ Tank(s) Pump		Liquid Level of 1			STACTORIAL TO
	cum measured.	ridulo revelor i	faifk in. Sludg	e Level in. Scum Level	in.
	d to be pumped? No (If no provide measures	Total (Sludge + :	Scum) / Liquid L	evel = %Sludge & Sc	um
	/			* Tank must be pumped i	Eshin min
	remove septage: Mai	<del></del>		is greater than 25%.	i tuis vaitie
Z. If maintenance	hole was used, were all co	vers securely replaced?	Yes No please ex	plain	
Explanation:					
3. If owner refuse them complete	es to allow a Subsurface S and sign the following s	ewage Treatment Systotatement:	em (SSTS) to be pumped	through the maintenance ho	le, have
L		(OWNOR'S Name) refuse t	a allow the removal of sul	entra de la compansión de	
hole. I understa	nd that removal of solids a	nd liquids through other	o allow the removal of Sol	ids and liquids through the ma	intenance
	ned as a leaky tank? exam			oerea mantenance,	
	Mo Verificatio Meth		K 1		
		4	Tiecosi		
-	No Verificatio Meth				
5. is there evidence damaged, crack	:e of tank leakage from a :ed, or structurally unsou	septic, holding, pretrea	itment or pump tank be	low the operating depth or ex	idence of
	Tank	Leaking Out	Leaking In	Cover Damage	
3	Septic/Holding Tank #1	Yes No	Yes No	Yes No	
3	Septic/Holding Tank #2	Yes No	Yes No	Yes No	
F	Pretreatment Tank	Yes No	Yes No	☐Yes ☐No	
P	Pump Tank	Yes No	Yes No	☐ Yes ☐ No	
6. How many gallo	ns of septage were remo	ved?			
Tank#1 (600)	Tank #2	Pretreatment Ta	nk Pi	mp Tank	
7. Other information	on: List any troubleshoot	ing, minor repairs cond	ucted tank safety conce	The on other consumption	
		g/iv / tcp2ii3 coita	acted, talls salety colle	itis, of other concerns.	
8. Certification: 1 h	ereby certify as a State of I	Minnesota certified SSTS	Maintainer that I nersonal	ly conducted the week	
an	d made the observations,	or directly supervised oth	ners in the performance of	this job.	
Maintainer's Name	e: Olson's Sewer Service,	Inc. Maintaine	r's Address: 17638 Lyons	Street NE, Forest Lake, MN	
Maintainer's Licen	ise #: 216 / Mainta	ainer's Phone #: 651-464	1-2082	,	
Maintain and Signa	THE M	7.		6/000	
Maintainer's Signa	itule 190 CC		Date: //	P/200)	