DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 17 6 Re	ason for Maintenance:	n 9566x	28824	
Property Address: 12275-20	5th St. N. P	roperty Owner's Name:	omi bee	•
Municipality: Marin	State Zip (Code GEC	Code/Property I.D. #:	2
What was done to the system?	e de la comba	Marij (ebr	somilated familiano a m	
Tank(s) Pumped				
Sludge and scum measured.	Liquid Level of	Tailk in. Slud	ge Level in. Scum Lev	el in.
Do tanks need to be pumped?	Total (Sludge +	Scum) / Liquid	level = % thedea 8	
Yes No (If no provide measure	ments)			
1. Access used to remove septage: Mai	intenance Hole 🔲 Othe	er (Go to #3 below)	* Tank must be pumped	d if this value
2. If maintenance hole was used, were all co	overs securely replaced?	Yes No please e	is greater than 25%.	
Explanation:				
3. If owner refuses to allow a Subsurface sthem complete and sign the following s	Sewage Treatment Syst	em (SSTS) to be pumpe	through the maintenance f	iole, have
l.		<i>a</i>		
	(owner's name), refuse t	o allow the removal of so	lids and liquids through the m	aintenance
hole. I understand that removal of solids a 4. Is the tank designed as a leaky tank? example of the solids are solids.	nia liquias through other	access points is not cons	idered maintenance.	
- Aug		uryweii, ieacning pit		
Tank#1 Yes No Verificatio Meth	ood Used:			¥-
Tank#2 Yes No Verificatio Meth	od Used:			(€
5. Is there evidence of tank leakage from a damaged, cracked, or structurally uncou	septic, holding, pretre	atment or pump tank be	low the operating dones	
damaged, cracked, or structurally unsou	nd maintenance hole o	overs?	over and operating deptit of t	evidence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	Yes No	Yes No	
Septic/Holding Tank #2	Yes No	Yes No	Yes No	ı
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	Yes No	☐ Yes No	Yes No	
. How many gallons of septage were remo	ved?			
Tank#1 ///// Tank#2 ///	Pretreatment Ta	nkPı	Imp Tank 200	
. Other information: List any troubleshooti	ing, minor repairs cond	ucted, tank safety conce	rns, or other concerns.	
Certification: I hereby certify as a State of A and made the observations,	Minnesota certified SSTS	Maintainer that I personal	ly conducted the work	
			• •	
Maintainer's Name: Olson's Sewer Service, I	nc. Maintaine	r's Address: 17638 Lyons	Street NE, Forest Lake, MN	
Maintainer's License #: 216 Mainta	iner's Phone #: 651-464	l-2082	ŧ	
Maintainer's Signature	1	Date: //	-6-22	