## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT K687642818 61

Date of Maintenance 7/20/22 Re	ason for Maintenance:			
Property Address: 12636-1824 55	N. P	roperty Owner's Name:	Sm& Paul Quale	
Municipality: Manne			Code/Property i.D.#:	
	1 6 116 7	Measurement (muscabe	ompleted if tanks NOT pumpe	
☑ Tank(s) Pumped	limidi and di	_ A.		en de la
Sludge and sour measured.	Liquid Level of	Tarik in. Sludg	e Level in. Scum Level	in
Do tanks need to be pumped?  Yes No (If no provide measure	Total (Sludge +	Scum) / Liquid L	evel = % Sludge & Scun	
Access used to remove septage:      Maintenance belowers used assessed assessed.			<ul> <li>Tank must be pumped if the sign of the si</li></ul>	nis valu
2. If maintenance hole was used, were all co	overs securely replaced?	Yes No please ex	plain	
Explanation:				
<ol><li>If owner refuses to allow a Subsurface them complete and sign the following s</li></ol>	Sewage Treatment Syst	em (SSTS) to be pumped	through the maintenance hole,	have
l,	racement.	8		
	(owner's name), refuse t	o allow the removal of sol	ids and liquids through the maint	enance
hole. I understand that removal of solids a 4. Is the tank designed as a leaky tank? example 1.	nie liquies through other	access points is not consi	dered maintenance.	
man and man and a				
Tank#1 Yes No Verificatio Meth	od Used: Clance	tank thr	ugh MH cover	
Tank#2 Tyes No Verificatio Meth	od Used: Cycus	new lift tank	. Though WHOL	352
5. Is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretrea	desant ou manus to all I. I.	ow the operating depth or evid	ver
damaged, cracked, or structurally unsou Tank	moniteligite fiole (	overs:		ciice oi
Septic/Holding Tank #1	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	
	I I I I I I I I I I I I I I I I I I I	I I YAC I INA I		
Pump Tank	□Yes ☑No		Yes No	
	Yes No	Yes No	Yes No	
6. How many gallons of septage were remo	ved?	☐ Yes ☑No		
6. How many gallons of septage were removed Tank #1 1200 Tank #2	ved?  Pretreatment Ta	Yes No	Yes No	
6. How many gallons of septage were remo	ved?  Pretreatment Ta	Yes No	Yes No	
6. How many gallons of septage were remore  Tank #1 Tank #2  7. Other information: List any troubleshooti	Pretreatment Ta	Yes No  Pu  nk Pu  ucted, tank safety conce	mp Tank 300	
6. How many gallons of septage were removed.  Tank #1	Pretreatment Taing, minor repairs condi	Yes No  No  Pu  ucted, tank safety conce	mp Tank 300	
<ul> <li>6. How many gallons of septage were removed.</li> <li>Tank #1</li></ul>	Pretreatment Taing, minor repairs conditions  Ainnesota certified SSTS In directly supervised other	Yes No  Pu  ucted, tank safety conce  Waintainer that I personall ers in the performance of	rns, or other concerns.  y conducted the work this job.	
7. Other information: List any troubleshooti  8. Certification: I hereby certify as a State of Mand made the observations, of Maintainer's Name: Olson's Sewer Service, I	Pretreatment Taing, minor repairs conditions  Ainnesota certified SSTS In directly supervised other	Yes No  No  Pu  ucted, tank safety conce	rns, or other concerns.  y conducted the work this job.	
Tank #1 Tank #2  7. Other information: List any troubleshooti  8. Certification: I hereby certify as a State of A and made the observations, of Maintainer's Name: Olson's Sewer Service, I	Pretreatment Taing, minor repairs conditions  Ainnesota certified SSTS In directly supervised other	Yes No  No  Pu  Lected, tank safety conce  Waintainer that I personall lers in the performance of  r's Address: 17638 Lyons:	rns, or other concerns.  y conducted the work this job.	
Tank #1 Tank #2  7. Other information: List any troubleshooti  8. Certification: I hereby certify as a State of A and made the observations, of Maintainer's Name: Olson's Sewer Service, I	Pretreatment Taing, minor repairs conditions  Minnesota certified SSTS I or directly supervised others.  Maintaine	Yes No  No  Pu  Lected, tank safety conce  Waintainer that I personall lers in the performance of  r's Address: 17638 Lyons:	rns, or other concerns.  y conducted the work this job.	