## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT M 8391 h 28822

Date of Main	tenance 10/13/82 Re	ason for Maintenance:			
Property Add	ress: 17751 Lomo.	nd Trail P	roperty Owner's Name:	Breat Reibel	-
Municipality:	Movine		iode <u>55047</u> GEO		Ť
the management of the second	was done lotthe sy temps		Marijoji ejeklatiker	ວັນກັງໄປໄຮ້ ໄປຂອກເຂົ້າເປັນ ຄົວກຳຄັນ	
Tank(s) Pu	-	Liquid Laura of	- 1		
Sludge and	scum measured.	Liquid Level of	Tarik in. Slude	ge Level in. Scum Level	in.
	eed to be pumped?  No (If no provide measure)	ments) Total (Słudge +	Scum) / Liquid	Level = %Sludge & Scu	ım
	to remove septage: - Mai		er (Go to #3 below)	* Tank must be pumped if	this value
	ce hole was used, were all co			is manatarally mass	
Explanation:				<i></i>	
3. If owner refu them comple	uses to allow a Subsurface S ete and sign the following s	sewage Treatment Syste tatement:	em (SSTS) to be pumped	through the maintenance hole	, have
1,		(OWNer's name) refuse t	o allow the removal of se	ltala a mail le e e e e e	
hole. I unders	stand that removal of solids a	nd liquids through other	access points is not cons	ids and liquids through the main	tenance
4. Is the tank de	signed as a leaky tank? exam	ple: seepage pit, cesspool,	drywell, leaching pit	idered maintenance.	
	es - No Verificatio Meth				
Tank#2 Y	es No Verificatio Meth	r#			9
5. Is there evide damaged, cra	nce of tank leakage from a cked, or structurally unsou	septic, holding, pretrea	ntment or pump tank be overs?	low the operating depth or evid	lence of
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes - No	Yes ANO	☐ Yes → No	
	Septic/Holding Tank #2	☐ Yes → No	Yes No	Yes Allo	
	Pretreatment Tank	Yes No	Yes No	Yes No	
•	Pump Tank	☐ Yes -► No	☐ Yes ☐ No	Yes No	
6. How many gal	ions of septage were remov	red?			
Tank#1 1000				mp Tank _385	
7. Other informat	tion: List any troubleshooti	ng, minor repairs condu	acted, tank safety conce	rns, or other concerns.	
8. Certification: 1	hereby certify as a State of N and made the observations, o	Minnesota certified SSTS A	Maintainer that I personal	y conducted the work	
	me: Olson's Sewer Service, I		•	Cris Job. Street NE, Forest Lake, MN	
Maintainer's Lice	ense #: 216 Mainta	iner's Phone #: 651-464		ii.	
Maintainer's Sig	nature 1		Date: 1.0	12/22	
	-		10/	1 ) / 00	